



**HEIDENHAIN**

**Pilot**

**TNC 426 B**  
**TNC 430**

**NC Software**  
**280 472-xx**  
**280 473-xx**







## The Pilot

... is your concise programming guide for the HEIDENHAIN TNC 426 B and TNC 430 contouring controls. For more comprehensive information on programming and operating, refer to the TNC User's Manual. There you will find complete information on:

- Q-parameter programming
- the central tool file
- 3D tool compensation
- tool measurement

Certain symbols are used in the Pilot to denote specific types of information:

	Important note
	Warning: danger for the user or the machine!
	The TNC and the machine tool must be prepared by the machine tool builder to perform these functions!
	Chapter in User's Manual where you will find more detailed information on the current topic.

The information in this Pilot applies to TNCs with the following software numbers:

Control	NC Software Number
TNC 426 CB, TNC 426 PB	280 472 06
TNC 426 CF*, TNC 426 PF*	280 473 06
TNC 430 CA, TNC 430 PA	280 472 06
TNC 430 CE*, TNC 430 PE*	280 473 06

\*) Export version

## Contents

Fundamentals .....	4
Contour Approach and Departure .....	13
Path Functions .....	18
FK Free Contour Programming .....	25
Subprograms and Program Section Repeats .....	33
Working with Cycles .....	36
Drilling Cycles .....	39
Pockets, Studs, and Slots .....	47
Point Patterns .....	56
SL Cycles .....	58
Multipass Milling .....	65
Coordinate Transformation Cycles .....	68
Special Cycles .....	74
Digitizing 3D Surfaces .....	77
Graphics and Status Displays .....	83
ISO Programming .....	86
Miscellaneous Functions M .....	91

# Fundamentals

## Programs/Files



See "Programming, File Management"

The TNC keeps its programs, tables and texts in files.  
A file designation consists of two components:

THREAD2.H

File name

Maximum length:  
16 characters

File type

see table at right

## Creating a New Part Program

PGM  
MGT

- ▶ Select the directory in which the program is stored
- ▶ Enter a new file name with file type
- ▶ Select unit of measure for dimensions (mm or inches)
- ▶ Define the blank form (BLK) for graphics:
  - ▶ Enter the spindle axis
  - ▶ Enter coordinates of the MIN point:  
the smallest X, Y and Z coordinates
  - ▶ Enter coordinates of the MAX point:  
the greatest X, Y and Z coordinates

**1 BLK FORM 0.1 Z X+0 Y+0 Z-50**

**2 BLK FORM 0.2 X+100 Y+100 Z+0**

### Files in the TNC

### File type

#### Programs

- in HEIDENHAIN format
- in ISO format

.H  
.I

#### Tables for


- Tools
- Datums
- Pallets
- Cutting data
- Points

.T  
.D  
.P  
.CDT  
.PNT

#### Texts as

- ASCII files

.A



# Choosing the Screen Layout



See "Introduction, the TNC 426 B, TNC 430"



► Show soft keys for setting the screen layout

Mode of operation	Screen contents	
Manual operation	Positions	POSITION
Electronic handwheel	Positions at left Status at right	POSITION + STATUS
Positioning with manual data input	Program	PGM
	Program at left Status at right	PGM + STATUS
Program run, full sequence	Program	PGM
Program run, single block test run	Program at left Program structure at right	PGM + SECTS
	Program at left Status at right	PGM + STATUS
	Program at left Graphics at right	PGM + GRAPHICS
	Graphics	GRAPHICS

Continued ►

Manual operation				Programming and editing	
ACTL.		<div><div>X</div><div>-50.0000</div></div> <div><div>Y</div><div>+250.0000</div></div> <div><div>Z</div><div>-150.0000</div></div> <div><div>A</div><div>+0.0000</div></div> <div><div>B</div><div>+180.0000</div></div> <div><div>C</div><div>+90.0000</div></div>		<div>DIST.</div> <div><div>X</div><div>+350.0000</div><div>C</div><div>+350.0000</div></div> <div><div>Y</div><div>+350.0000</div></div> <div><div>Z</div><div>+350.0000</div></div> <div><div>A</div><div>+350.0000</div></div> <div><div>B</div><div>+90.0000</div></div> <div><div><div><div></div></div></div><div><div>A</div><div>+0.0000</div></div><div><div>B</div><div>+180.0000</div></div><div><div>C</div><div>+90.0000</div></div></div> <div><div><div><div></div></div></div><div>Basic rotation</div><div>+0.0000</div></div>	
<div><div></div></div> <div>T</div>		<div>F 0</div>		<div>M 5/9</div>	
M		S		F	
TOUCH PROBE		DATUM SET		INCRE- MENT <div>OFF</div> / ON	
3D ROT		<div><div></div></div>		TOOL TABLE	
<div>▲ Positions at left, status at right</div> <div>▲ Program at left, graphics at right</div>					
Manual operation		Programming and editing			
<div>0 BEGIN PGM 3516 MM</div> <div>1 BLK FORM 0.1 Z X-90 Y-90 Z-40</div> <div>2 BLK FORM 0.2 X+90 Y+90 Z+0</div> <div>3 TOOL CALL 1 Z S1400</div> <div>4 L Z+50 R0 F MAX</div> <div>5 CALL LBL 1</div> <div>6 L Z+100 R0 F MAX M2</div> <div>7 LBL 1</div> <div>8 L X+0 Y+90 RL F250</div> <div>9 FPDL X+0 Y+0</div> <div>10 FC DR- R80 CCX+0 CCY+0</div> <div>11 FCT DR- R7.5</div> <div>12 FCT DR+ R90 CCX+69.282 CCY-40</div> <div>13 FSELECT 2 ; Vorschlag 1 entspricht nicht der Zeichnung!</div>		<div></div>			
BEGIN		END		PAGE	
<div><div></div></div>		<div><div></div></div>		<div><div></div></div>	
FIND		START		START SINGLE	
				<div><div></div></div>	
RESET		STAR			

T

F 0

M 5/9

Mode of operation	Screen contents
Programming and editing	<div>Program</div> <div>PGM</div>
	<div>Program at left</div> <div>Program structure at right</div> <div>PGM + SECTS</div>
	<div>Program at left</div> <div>Programming graphics at right</div> <div>PGM + GRAPHICS</div>

Manual operation	Programming and editing					
<pre> 0 BEGIN PGM 1GB MM 1 BLK FORM 0.1 Z X+0 Y+0 Z-40 2 BLK FORM 0.2 X+100 Y+100 Z+0 3 * - Make hole pattern ID 27943KL1 4 TOOL CALL 1 Z S4500 5 L Z+100 R0 F MAX 6 CYCL DEF 203 UNIVERSL DRILLNG   0200=2  \$SET-UP CLEARANCE   0201=-50 \$DEPTH   0206=250 \$FEED RATE FOR PLNGNG   0202=0  \$PLUNGING DEPTH   0210=0  \$DWELL TIME AT TOP   0203=+0 \$SURFACE COORDINATE   0204=100 \$2ND SET-UP CLEARANCE   0212=0  \$DECREMENT </pre>	<pre> BEGIN PGM 1GB - Make hole pattern ID 27943KL1 - Parameter definition - Make pocket   - Rough out   - Finishing - Make hole pattern   - Center drill   - Pecking   - Tapping END PGM 1GB </pre>					
	<div>BEGIN</div> <div>↑</div>	<div>END</div> <div>↓</div>	<div>PAGE</div> <div>↑</div>	<div>PAGE</div> <div>↓</div>	<div>FIND</div> <div></div>	<div>CHANGE WINDOW</div> <div>↔</div>

▲ Program at left, program structure at right

## Absolute Cartesian Coordinates


The dimensions are measured from the current datum.  
The tool moves to the absolute coordinates.

Programmable axes in an NC block

Linear motion: 5 axes

Circular motion: 2 linear axes in a plane or


3 linear axes with cycle 19 WORKING PLANE



## Incremental Cartesian Coordinates

The dimensions are measured from the last programmed position of the tool.

The tool moves by the incremental coordinates.




### Circle Center and Pole: CC

The circle center (CC) must be entered to program circular tool movements with the path function C (see page 21). CC is also needed to define the pole for polar coordinates.

CC is entered in Cartesian coordinates\*.

An absolutely defined circle center or pole is always measured from the workpiece datum.


An incrementally defined circle center or pole is always measured from the last programmed position of the workpiece.



### Angle Reference Axis

Angles – such as a polar coordinate angle PA or an angle of rotation ROT – are measured from the angle reference axis.

Working plane	Ref. axis and 0° direction
X/Y	X
Y/Z	Y
Z/X	Z



\*Circle center in polar coordinates: See FK programming



## Polar Coordinates

Dimensions in polar coordinates are referenced to the pole (CC).

A position in the working plane is defined by

- Polar coordinate radius PR = Distance of the position from the pole (CC).
- Polar coordinate angle PA = Angle from the angle reference axis to the straight line CC – PR

### Incremental dimensions

Incremental dimensions in polar coordinates are measured from the last programmed position.

### Programming polar coordinates




► Select the path function



► Press the P key

► Answer the dialog prompts



## Defining Tools


### Tool data

Every tool is designated by a tool number between 1 and 254 or, if you are using tool tables, by a tool name.

### Entering tool data

You can enter the tool data (length L and radius R)

- in a tool table (centrally, Program TOOL.T)
- or
- within the part program in TOOL DEF blocks (locally)



## TOOL DEF

- ▶ Tool number
  - ▶ Tool length L
  - ▶ Tool radius R
- ▶ Program the tool length as its difference  $\Delta L$  to the zero tool:
- $\Delta L > 0$ : The tool is longer than the zero tool
  - $\Delta L < 0$ : The tool is shorter than the zero tool
- ▶ With a tool presetter you can measure the actual tool length, then program that length.

## Calling the tool data

## TOOL CALL

- ▶ Tool number or name
- ▶ Working spindle axis: tool axis
- ▶ Spindle speed S
- ▶ Feed rate
- ▶ Tool length override DL (e.g. to compensate wear)
- ▶ Tool radius override DR (e.g. to compensate wear)

**3 TOOL DEF 6 L+7.5 R+3**

**4 TOOL CALL 6 Z S2000 F650 DL+1 DR+0.5**


**5 L Z+100 R0 FMAX**

**6 L X-10 Y-10 R0 FMAX M6**


## Tool change



- Beware of tool collision when moving to the tool change position!
- The direction of spindle rotation is defined by M function:  
M3: Clockwise  
M4: Counterclockwise
- The maximum permissible override for tool radius or length is  $\pm 99.999$  mm!



## ▼ Oversizes on an end mill



## Tool Compensation

The TNC compensates the length  $L$  and radius  $R$  of the tool during machining.

Length compensation

Beginning of effect:

- Tool movement in the spindle axis

End of effect:

- Tool exchange or tool with the length  $L=0$

Radius compensation

Beginning of effect:


- Tool movement in the working plane with  $RR$  or  $RL$

End of effect:


- Execution of a positioning block with  $R0$

Working without radius compensation (e.g. drilling):

- Tool movement with  $R0$




▼ S = Start; E = End



## Datum Setting Without a 3D Touch Probe

During datum setting you set the TNC display to the coordinates of a known position on the workpiece:

- ▶ Insert a zero tool with known radius
- ▶ Select the manual operation or electronic handwheel mode
- ▶ Touch the reference surface in the tool axis with the tool and enter its length
- ▶ Touch the reference surface in the working plane with the tool and enter the position of the tool center



## Datum Setting with a 3D Touch Probe

The fastest, simplest and most accurate way to set a datum is to use a HEIDENHAIN 3D touch probe.

The following probe functions are provided by the manual operation or electronic handwheel modes of operation:



Basic rotation




Datum setting in one axis



Datum setting at a corner



Datum setting at a circle center



# Contour Approach and Departure

Starting point  $P_S$

$P_S$  lies outside of the contour and must be approached without radius compensation.

Auxiliary point  $P_H$

$P_H$  lies outside of the contour and is calculated by the TNC.



The tool moves from the starting point  $P_S$  to the auxiliary point  $P_H$  at the feed rate last programmed feed rate!

First contour point  $P_A$  and last contour point  $P_E$

The first contour point  $P_A$  is programmed in the APPR (approach) block.  
The last contour point is programmed as usual.

End point  $P_N$

$P_N$  lies outside of the contour and results from the DEP (departure) block.  $P_N$  is automatically approached with  $R0$ .

## Path Functions for Approach and Departure

**APPR**  
**DEP**

► Press the soft key with the desired path function:



Straight line with tangential connection



Straight line perpendicular to the contour point




Circular arc with tangential connection



Straight line segment tangentially connected to the contour through an arc



- Program a radius compensation in the APPR block!
- DEP blocks set the radius compensation to 0!



## Approaching on a Straight Line with Tangential Connection




- Coordinates for the first contour point  $P_A$
- Distance Len (length) from  $P_H$  to  $P_A$   
Enter a length  $Len > 0$
- Tool radius compensation RR/RL

7 L X+40 Y+10 R0 FMAX M3

8 APPR LT X+20 Y+20 LEN 15 RR F100

9 L X+35 Y+35



## Approaching on a Straight Line Perpendicular to the First Contour Element




- Coordinates for the first contour point  $P_A$
- Distance Len (length) from  $P_H$  to  $P_A$   
Enter a length  $Len > 0$
- Tool radius compensation RR/RL

7 L X+40 Y+10 R0 FMAX M3

8 APPR LN X+10 Y+20 LEN 15 RR F100

9 L X+20 Y+35




## Approaching Tangentially on an Arc



- Coordinates for the first contour point  $P_A$
- Radius  $R$   
Enter a radius  $R > 0$
- Circle center angle (CCA)  
Enter a CCA  $> 0$
- Tool radius compensation  $RR/RL$

```
7 L X+40 Y+10 R0 FMAX M3
8 APPR CT X+10 Y+20 CCA 180 R10 RR F100
9 L X+20 Y+35
```




## Approaching Tangentially on an Arc and a Straight Line



- Coordinates for the first contour point  $P_A$
- Radius  $R$   
Enter a radius  $R > 0$
- Tool radius compensation  $RR/RL$

```
7 L X+40 Y+10 R0 FMAX M3
8 APPR LCT X+10 Y+20 R10 RR F100
9 L X+20 Y+35
```



## Departing Tangentially on a Straight Line




► Distance Len (length) from  $P_E$  to  $P_N$   
Enter a length Len > 0

23 L X+30 Y+35 RR F100

24 L Y+20 RR F100

25 DEP LT LEN 12.5 F100 M2



## Departing on a Straight Line Perpendicular to the Last Contour Element




► Distance Len (length) from  $P_E$  to  $P_N$   
Enter a length Len > 0

23 L X+30 Y+35 RR F100

24 L Y+20 RR F100

25 DEP LN LEN+20 F100 M2






## Departing Tangentially on an Arc



- ▶ Radius R  
Enter a radius  $R > 0$
- ▶ Circle center angle (CCA)

```
23 L X+30 Y+35 RR F100
24 L Y+20 RR F10
25 DEP CT CCA 180 R+8 F100 M2
```




## Departing on an Arc Tangentially Connecting the Contour and a Straight Line



- ▶ Coordinates of the end point  $P_N$
- ▶ Radius R  
Enter a radius  $R > 0$

```
23 L X+30 Y+35 RR F100
24 L Y+20 RR F100
25 DEP LCT X+10 Y+12 R8 F100 M2
```



# Path Functions for Positioning Blocks



See „Programming: Programming contours“.

## Programming the Direction of Traverse

Regardless of whether the tool or the workpiece is actually moving, you always program as if the tool is moving and the workpiece is stationary.

## Entering the Target Positions

Target positions can be entered in Cartesian or polar coordinates – either as absolute or incremental values, or with both absolute and incremental values in the same block.

## Entries in the Positioning Block

A complete positioning block contains the following data:

- Path function
- Coordinates of the contour element end points (target position)
- Radius compensation RR/RL/R0
- Feed rate F
- Miscellaneous function M



Before you execute a part program, always pre-position the tool to prevent the possibility of damaging the tool or workpiece!

## Path functions

Straight line



Page 19

Chamfer between two straight lines



Page 20

Corner rounding



Page 20

Circle center or pole for polar coordinates



Page 21

Circular path around the circle center CC



Page 21

Circular path with known radius



Page 22

Circular path with tangential connection to previous contour



Page 23

FK Free Contour Programming



Page 25

## Straight Line




- ▶ Coordinates of the straight line end point
- ▶ Tool radius compensation RR/RL/R0
- ▶ Feed rate F
- ▶ Miscellaneous function M

With Cartesian coordinates:

```
7 L X+10 Y+40 RL F200 M3
```

```
8 L IX+20 IY-15
```

```
9 L X+60 IY-10
```



With polar coordinates:


```
12 CC X+45 Y+25
```

```
13 LP PR+30 PA+0 RR F300 M3
```

```
14 LP PA+60
```

```
15 LP IPA+60
```

```
16 LP PA+180
```



- You must first define the pole CC before you can program polar coordinates!
- Program the pole CC only in Cartesian coordinates!
- The pole CC remains effective until you define a new one!

## Inserting a Chamfer Between Two Straight Lines



► Chamfer side length

```
7 L X+0 Y+30 RL F300 M3
```


```
8 L X+40 IY+5
```

```
9 CHF 12 F250
```

```
10 L IX+5 Y+0
```



- You cannot start a contour with a CHF block!
- The radius compensation before and after the CHF block must be the same!
- An inside chamfer must be large enough to accommodate the current tool!



## Corner Rounding

The beginning and end of the arc extend tangentially from the previous and subsequent contour elements.



► Radius R of the circular arc

► Feed rate F for corner rounding

```
5 L X+10 Y+40 RL F300 M3
```


```
6 L X+40 Y+25
```

```
7 RND R5 F100
```

```
8 L X+10 Y+5
```



- An inside arc must be large enough to accommodate the current tool!



## Circular Path Around the Circle Center CC



► Coordinates of the circle center CC



► Coordinates of the arc end point

► Direction of rotation DR

C and CP enable you to program a complete circle in one block.

With cartesian coordinates:

```
5 CC X+25 Y+25
```

```
6 L X+45 Y+25 RR F200 M3
```

```
7 C X+45 Y+25 DR+
```

With polar coordinates:



```
18 CC X+25 Y+25
```

```
19 LP PR+20 PA+0 RR F250 M3
```

```
20 CP PA+180 DR+
```



- Define the pole CC before programming polar coordinates!
- Program the pole CC only in Cartesian coordinates!
- The pole CC remains effective until you define a new one!
- The arc end point can be defined only with the polar coordinate angle (PA)!



## Circular Path with Known Radius (CR)



- Coordinates of the arc end point
- Radius R
  - If the central angle ZW > 180, R is negative.
  - If the central angle ZW < 180, R is positive.
- Direction of rotation DR

10 L X+40 Y+40 RL F200 M3 Arc starting point


11 CR X+70 Y+40 R+20 DR- Arc 1 or

11 CR X+70 Y+40 R+20 DR+ Arc 2

10 L X+40 Y+40 RL F200 M3 Arc starting point


11 CR X+70 Y+40 R-20 DR- Arc 3 or

11 CR X+70 Y+40 R-20 DR+ Arc 4



▲ Arcs 1 and 2

▼ Arcs 3 and 4



## Circular Path CT with Tangential Connection



- Coordinates of the arc end point
- Radius compensation RR/RL/R0
- Feed rate F
- Miscellaneous function M

With cartesian coordinates:



```
5 L X+0 Y+25 RL F250 M3
6 L X+25 Y+30
7 CT X+45 Y+20
8 L Y+0
```

With polar coordinates:

```
12 CC X+40 Y+35
13 L X+0 Y+35 RL F250 M3
14 LP PR+25 PA+120
15 CTP PR+30 PA+30
16 L Y+0
```



- Define the pole CC before programming polar coordinates!
- Program the pole CC only in Cartesian coordinates!
- The pole CC remains effective until you define a new one!



## Helix (Only in Polar Coordinates)

Calculations (upward milling direction)

Path revolutions:  $n$  = Thread revolutions + overrun at start and end of thread

Total height:  $h$  = Pitch  $P$  x path revolutions  $n$

Incr. coord. angle:  $IPA$  = Path revolutions  $n$  x  $360^\circ$

Start angle:  $PA$  = Angle at start of thread + angle for overrun

Start coordinate:  $Z$  = Pitch  $P$  x (thread revolutions + thread overrun at start of thread)

Shape of helix

Internal thread	Work direction	Direction	Radius comp.
Right-hand	Z+	DR+	RL
Left-hand	Z+	DR-	RR
Right-hand	Z-	DR-	RR
Left-hand	Z-	DR+	RL
External thread			
Right-hand	Z+	DR+	RR
Left-hand	Z+	DR-	RL
Right-hand	Z-	DR-	RL
Left-hand	Z-	DR+	RR



M6 x 1 mm thread with 5 revolutions:

**12 CC X+40 Y+25**

**13 L Z+0 F100 M3**

**14 LP PR+3 PA+270 RL**

**15 CP IPA-1800 IZ+5 DR- RL F50**





# FK Free Contour Programming



See "Programming Tool Movements – FK Free Contour Programming"


If the end point coordinates are not given in the workpiece drawing or if the drawing gives dimensions that cannot be entered with the gray path function keys, you can still program the part by using the "FK Free Contour Programming."

Possible data on a contour element:

- Known coordinates of the end point
- Auxiliary points on the contour element
- Auxiliary points near the contour element
- A reference to another contour element
- Directional data (angle) / position data
- Data regarding the course of the contour

To use FK programming properly:

- All contour elements must lie in the working plane.
- Enter all available data on each contour element.
- If a program contains both FK and conventional blocks, the FK contour must be fully defined before you can return to conventional programming.



▲ These dimensions can be programmed with FK

## Working with the Interactive Graphics



Select the PGM+GRAPHICS screen layout!

The interactive graphics show the contour as you are programming it. If the data you enter can apply to more than one solution, the following soft keys will appear:

SHOW SOLUTION	To show the possible solutions
SELECT SOLUTION	To enter the displayed solution in the part program
END SELECT	To enter data for subsequent contour elements
START SINGLE <input type="checkbox"/>	To graphically display the next programmed block

Standard colors of the interactive graphics

Fully defined contour element

The displayed element is one of a limited number of possible solutions

The element is one of an infinite number of solutions

Contour element from a subprogram



Manual operation	Programming and editing						
14 RND R2.5							
15 FL AN+0.975							
16 FCT DR+ R10.5 CCX+0 CCY+0							
17 FLT AN+89.025							
18 FCT DR+ R2.5 CLSD-							
19 END PGM 35071 MM							
SHOW SOLUTION	SELECT SOLUTION					START SINGLE <input type="checkbox"/>	END SELECT

## Initiating the FK Dialog



Initiate the FK dialog

### Straight Circular



Contour element without tangential connection



Contour element with tangential connection



Pole for FK programming

### End Point Coordinates X, Y or PA, PR



Cartesian coordinates X and Y



Polar coordinates referenced to FPOL




Incremental input

```
7 FPOL X+20 Y+30
```

```
8 FL IX+10 Y+20 RR F100
```

```
9 FCT PR+15 IPA+30 DR+ R15
```



## Circle Center (CC) in an FC/FCT block



Cartesian coordinates of the circle center



Polar coordinates of the circle center  
referenced to FPOL




Incremental input

10 FC CCX+20 CCY+15 DR+ R15

11 FPOL X+20 Y+15

...

13 FC DR+ R15 CCPR+35 CCPA+40



## Auxiliary Points

... P1, P2, P3 on a contour



For straight lines: up to 2 auxiliary points  
For circles: up to 3 auxiliary points

... next to a contour




Coordinates of the auxiliary points



Perpendicular distance

13 FC DR- R10 P1X+42.929 P1Y+60.071

14 FLT AN-70 PDX+50 PDY+53 D10



## Direction and Length of the Contour Element

Data on a straight line



Gradient angle of a straight line



Length of a straight line

Data on a circular path



Gradient angle of the entry tangent



Length of an arc chord

```
27 FLT X+25 LEN 12.5 AN+35 RL F200
```

```
28 FC DR+ R6 LEN 10 AN-45
```

```
29 FCT DR- R15 LEN 15
```

Identifying a closed contour



Beginning: CLSD+



End: CLSD-

```
12 L X+5 Y+35 RL F500 M3
```

```
13 FC DR- R15 CLSD+ CCX+20 CCY+35
```

```
...
```

```
17 FCT DR- R+15 CLSD-
```





## Values Relative to Block N: Direction and Distance of the Contour Element


- RAN  $\text{[N]}$  Gradient angle
- PAR  $\text{[N]}$  Parallel to a straight contour element  
Parallel to the entry tangent of an arc
- DP  $\text{[N]}$  Distance from a parallel element



Always enter relative values incrementally!

```

17 FL LEN 20 AN+15
18 FL AN+105
19 FL LEN 12.5 PAR 17 DP 12.5
20 FSELECT 2
21 FL LEN 20 IAN+95
22 FL IAN+220 RAN 18
    
```



## Values Relative to Block N: Circle Center CC



Cartesian coordinates of a circle center relative to block N



Polar coordinates of the circle center relative to block N



Always enter relative data as incremental values!

12 FL X+10 Y+10 RL

13 FL ...


14 FL X+18 Y+35

15 FL ...

16 FL ...

17 FC DR- R10 CCA+0 ICCX+20 ICCY-15

RCCX12 RCCY14





# Subprograms and Program Section Repeats

Subprograms and program section repeats enable you to program a machining sequence once and then run it as often as needed.

## Working with Subprograms

- 1 The main program runs up to the subprogram call CALL LBL1.
- 2 The subprogram—labeled with LBL1—runs through to its end LBL0.
- 3 The main program resumes.

It's good practice to place subprograms after the main program end (M2).




- Answer the dialog prompt REP with the NOENT key!
- You cannot call LBL0!

## Working with Program Section Repeats


- 1 The main program runs up to the call for a section repeat CALL LBL1 REP2/2.
- 2 The program section between LBL1 and CALL LBL1 REP2/2 is repeated the number of times indicated with REP.
- 3 After the last repetition the main program resumes.



Altogether, the program section is run once more than the number of programmed repeats!



◆ S = Jump; R = Return jump




## Subprogram Nesting:

## A Subprogram within a Subprogram

- 1 The main program runs up to the first subprogram call CALL LBL1.
- 2 Subprogram 1 runs up to the second subprogram call CALL LBL2.
- 3 Subprogram 2 runs to its end.
- 4 Subprogram 1 resumes and runs to its end.
- 5 The main program resumes.



- A subprogram cannot call itself!
- Subprograms can be nested up to a maximum depth of 8 levels!




S = Jump; R = Return jump ►

## Any Program as a Subprogram

- 1 The calling program A runs up to the program call CALL PGM B.
- 2 The called program B runs through to its end.
- 3 The calling program A resumes.



The called program must not end with M2 or M30!



▲ S = Jump; R = Return jump

# Working with Cycles

Certain frequently needed machining sequences are stored in the TNC as cycles. Coordinate transformations and some special functions are also available as cycles.



- In a cycle, positioning data entered in the tool axis are always incremental, even without the I key!
- The algebraic sign of the cycle parameter depth determines the working direction!

Example

```
6 CYCL DEF 1.0 PECKING
7 CYCL DEF 1.1 SET UP 2
8 CYCL DEF 1.2 DEPTH -15
9 CYCL DEF 1.3 PECKG 10
...
```

Feed rates are entered in mm/min, the dwell time in seconds.

Defining cycles



► Select the desired cycle:



► Select the cycle group



► Select the cycle

## Drilling Cycles

1	PECKING	Page 39
200	DRILLING	Page 40
201	REAMING	Page 41
202	BORING	Page 42
203	UNIVERSAL DRILLING	Page 43
204	COUNTERBORE BACK	Page 44
2	TAPPING	Page 45
17	RIGID TAPPING	Page 46
18	THREAD CUTTING	Page 46

## Pockets, Studs, and Slots

4	POCKET MILLING	Page 47
212	POCKET FINISHING	Page 48
213	STUD FINISHING	Page 49
5	CIRCULAR POCKET MILLING	Page 50
214	CIRCULAR POCKET FINISHING	Page 51
215	CIRCULAR STUD FINISHING	Page 52
3	SLOT MILLING	Page 53
210	SLOT WITH RECIP. PLUNGE	Page 54
211	CIRCULAR SLOT	Page 55

## Point Patterns

220	CIRCULAR PATTERN	Page 56
221	LINEAR PATTERN	Page 57

Continued on next page ►

**SL Cycles**

14	CONTOUR GEOMETRY	Page 59
20	CONTOUR DATA	Page 60
21	PILOT DRILLING	Page 61
22	ROUGH-OUT	Page 61
23	FLOOR FINISHING	Page 62
24	SIDE FINISHING	Page 62
25	CONTOUR TRAIN	Page 63
27	CYLINDER SURFACE	Page 64

**Multipass Milling**

30	RUN DIGITIZED DATA	Page 65
230	MULTIPASS MILLING	Page 66
231	RULED SURFACE	Page 67

**Cycles for Coordinate Transformations**

7	DATUM SHIFT	Page 68
8	MIRROR IMAGE	Page 69
10	ROTATION	Page 70
19	WORKING PLANE	Page 71
11	SCALING FACTOR	Page 72
26	AXIS-SPECIFIC SCALING	Page 73

**Special Cycles**

9	DWELL TIME	Page 74
12	PGM CALL	Page 74
13	ORIENTED SPINDLE STOP	Page 75
32	TOLERANCE	Page 76

Graphic Support During Cycle Programming  
As you create a program, the TNC provides you with graphic illustrations of the input parameters.

### Calling a Cycle

The following cycles are effective as soon as they are defined:

- Cycles for coordinate transformations
- DWELL TIME cycle
- The SL cycles CONTOUR GEOMETRY and CONTOUR DATA
- Point patterns
- FAST CONTOUR MILLING Cycle

All other cycles go into effect when they are called through

- CYCL CALL: effective for one block
- M99: effective for one block
- M89: effective until canceled (depends on machine parameter settings)


Manual operation	Programming and editing
	Set-up clearance?
<pre> 1 BLK FORM 0.1 Z X+0 Y+0 Z-40 2 BLK FORM 0.2 X+100 Y+100 Z+0 3 TOOL CALL 1 Z S2500 4 L Z+100 R0 F MAX 5 CYCL DEF 203 UNIVERSAL DRILLING   Q200=2          ;SET-UP CLEARANCE   Q201=-20        ;DEPTH   Q206=150        ;FEED RATE FOR PLNGNG   Q202=5          ;PLUNGING DEPTH   Q210=0          ;DWELL TIME AT TOP   Q203=+0         ;SURFACE COORDINATE   Q204=50         ;2ND SET-UP CLEARANCE   Q212=0          ;DECREMENT   Q213=0          ;NR OF BREAKS   Q205=0          ;MIN. PLUNGING DEPTH </pre>	

# Drilling Cycles


## PECKING (1)

- ▶ CYCL DEF: Select Cycle 1 PECKING
  - ▶ Set-up clearance: A
  - ▶ Total hole depth (distance from the workpiece surface to the bottom of the hole): B
  - ▶ Pecking depth: C
  - ▶ Dwell time in seconds
  - ▶ Feed rate F

If the total hole depth is greater than or equal to the pecking depth, the tool drills the entire hole in one plunge.




```
6 CYCL DEF 1.0 PECKING
7 CYCL DEF 1.1 SET UP +2
8 CYCL DEF 1.2 DEPTH -15
9 CYCL DEF 1.3 PECKG +7.5
10 CYCL DEF 1.4 DWELL 1
11 CYCL DEF 1.5 F80
12 L Z+100 R0 FMAX M6
13 L X+30 Y+20 FMAX M3
14 L Z+2 FMAX M99
15 L X+80 Y+50 FMAX M99
16 L Z+100 FMAX M2
```



## DRILLING (200)

- ▶ CYCL DEF: Select Cycle 200 DRILLING
  - ▶ Set-up clearance: Q200
  - ▶ Depth – Distance between workpiece surface and bottom of hole: Q201
  - ▶ Feed rate for plunging: Q206
  - ▶ Pecking depth: Q202
  - ▶ Dwell time at top: Q210
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204

The TNC automatically pre-positions the tool in the tool axis. If the depth is greater than or equal to the pecking depth, the tool drills to the depth in one plunge.



## 11 CYCL DEF 200 DRILLING

Q200 = 2 ;SET-UP CLEARANCE

Q201 = -15 ;DEPTH

Q206 = 250 ;FEED RATE FOR PLUNGING

Q202 = 5 ;PLUNGING DEPTH

Q210 = 0 ;DWELL TIME AT TOP

Q203 = +0 ;SURFACE COORDINATE

Q204 = 100 ;2ND SET-UP CLEARANCE


12 L Z+100 R0 FMAX M6

13 L X+30 Y+20 FMAX M3

14 CYCL CALL

15 L X+80 Y+50 FMAX M99

16 L Z+100 FMAX M2






## REAMING (201)


- ▶ CYCL DEF: Select Cycle 201 REAMING
  - ▶ Set-up clearance: Q200
  - ▶ Depth – Distance between workpiece surface and bottom of hole: Q201
  - ▶ Feed rate for plunging: Q206
  - ▶ Dwell time at depth: Q211
  - ▶ Retraction feed rate: Q208
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204

The TNC automatically pre-positions the tool in the tool axis.



```

11 CYCL DEF 201 REAMING
    Q200 = 2      ;SET-UP CLEARANCE
    Q201 = -15    ;DEPTH
    Q206 = 100    ;FEED RATE FOR PLUNGING
    Q211 = 0.5    ;DWELL TIME AT DEPTH
    Q208 = 250    ;RETRACTION FEED RATE
    Q203 = +0     ;SURFACE COORDINATE
    Q204 = 100    ;2ND SET-UP CLEARANCE
12 L Z+100 R0 FMAX M6
13 L X+30 Y+20 FMAX M3
14 CYCL CALL
15 L X+80 Y+50 FMAX M99
16 L Z+100 FMAX M2
  
```





## BORING (202)



Danger of collision! Choose a disengaging direction that moves the tool away from the wall of the hole.

- ▶ CYCL DEF: Select Cycle 202 BORING
  - ▶ Set-up clearance: Q200
  - ▶ Depth – Distance between workpiece surface and bottom of hole: Q201
  - ▶ Feed rate for plunging: Q206
  - ▶ Dwell time at depth: Q211
  - ▶ Retraction feed rate: Q208
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204
  - ▶ Disengaging directn (0/1/2/3/4) at bottom of hole: Q214

The TNC automatically pre-positions the tool in the tool axis.



### 11 CYCL DEF 202 BORING

Q200 = 2 ;SET-UP CLEARANCE

Q201 = -15 ;DEPTH

Q206 = 100 ;FEED RATE FOR PLUNGING

Q211 = 0.5 ;DWELL TIME AT DEPTH

Q208 = 250 ;RETRACTION FEED RATE

Q203 = +0 ;SURFACE COORDINATE

Q204 = 100 ;2ND SET-UP CLEARANCE

Q214 = 1 ;DISENGAGING DIRECTN

12 L Z+100 R0 FMAX M6

13 L X+30 Y+20 FMAX M3


14 CYCL CALL

15 L X+80 Y+50 FMAX M99

16 L Z+100 FMAX M2

## UNIVERSAL DRILLING (203)

- ▶ CYCL DEF: Select Cycle 203 UNIVERSAL DRILLING
  - ▶ Set-up clearance: Q200
  - ▶ Depth – Distance between workpiece surface and bottom of hole: Q201
  - ▶ Feed rate for plunging: Q206
  - ▶ Pecking depth: Q202
  - ▶ Dwell time at top: Q210
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204
  - ▶ Decrement after each pecking depth: Q212
  - ▶ Nr of breaks – Number of chip breaks before retraction: Q213
  - ▶ Min. pecking depth if a decrement has been entered: Q205
  - ▶ Dwell time at depth: Q211
  - ▶ Retraction feed rate: Q208





The TNC automatically pre-positions the tool in the tool axis. If the depth is greater than or equal to the pecking depth, the tool drills to the depth in one plunge.

COUNTERBORE BACK (204)

- ▶ CYCL DEF: Select Cycle 204 COUNTERBORE BACK
- ▶ Set-up clearance: Q200
- ▶ Depth of counterbore: Q249
- ▶ Material thickness: Q250
- ▶ Tool edge off-center distance: Q251
- ▶ Tool edge height: Q252
- ▶ Feed rate for pre-positioning: Q253
- ▶ Feed rate for counterboring: Q254
- ▶ Dwell time at counterbore floor: Q255
- ▶ Workpiece surface coordinate: Q203
- ▶ 2nd set-up clearance: Q204
- ▶ Disengaging direction (0/1/2/3/4): Q214



- Danger of collision! Select the disengaging direction that gets the tool clear of the counterbore floor!
- Use this cycle only with a reverse boring bar!



11	CYCL DEF 204	COUNTERBORE BACK
	Q200 = 2	;SET-UP CLEARANCE
	Q249 = +5	;DEPTH OF COUNTERBORE
	Q250 = 20	;MATERIAL THICKNESS
	Q251 = 3.5	;OFF-CENTER DISTANCE
	Q252 = 15	;TOOL EDGE HEIGHT
	Q253 = 750	;F PRE-POSITIONING
	Q254 = 200	;F COUNTERBORING
	Q255 = 0.5	;DWELL TIME
	Q203 = +0	;SURFACE COORDINATE
	Q204 = 50	;2ND SET-UP CLEARANCE
	Q214 = 1	;DISENGAGING DIRECTN



## TAPPING with Floating Tap Holder (2)

- ▶ Insert the floating tap holder
- ▶ CYCL DEF: Select cycle 2 TAPPING
  - ▶ Set-up clearance: A
  - ▶ Total hole depth (thread length = distance between the workpiece surface and the end of the thread): B
  - ▶ Dwell time in seconds (a value between 0 and 0.5 seconds)
  - ▶ Feed rate F = Spindle speed S x thread pitch P



For tapping right-hand threads, actuate the spindle with M3,  
for left-hand threads use M4!

```
25 CYCL DEF 2.0 TAPPING
26 CYCL DEF 2.1 SET UP 3
27 CYCL DEF 2.2 DEPTH -20
28 CYCL DEF 2.3 DWELL 0.4
29 CYCL DEF 2.4 F100
30 L Z+100 R0 FMAX M6
31 L X+50 Y+20 FMAX M3
32 L Z+3 FMAX M99
```



## RIGID TAPPING (17)




- Machine and TNC must be prepared by the machine tool builder to perform rigid tapping!
- In rigid tapping, the spindle speed is synchronized with the tool axis feed rate!

## ► CYCL DEF: Select cycle 17 RIGID TAPPING

- Set-up clearance: A
- Tapping depth (distance between workpiece surface and end of thread): B
- Pitch: C

The algebraic sign determines the direction of the thread:

- Right-hand thread: +
- Left-hand thread: -



## THREAD CUTTING (18)




- The machine and TNC must be prepared by the machine tool builder for THREAD CUTTING!
- The spindle speed is synchronized with the tool axis feed rate!

## ► CYCL DEF: Select cycle 18 THREAD CUTTING

- Depth (distance between workpiece surface and end of thread): B
- Pitch: C

The algebraic sign:

- Right-hand thread: +
- Left-hand thread: -



# Pockets, Studs, and Slots

## POCKET MILLING (4)



This cycle requires either a center-cut end mill (ISO 1641) or pilot drilling at the pocket center!

The tool begins milling in the positive axis direction of the longer side. In square pockets it moves in the positive Y direction.

- ▶ The tool must be pre-positioned over the center of the slot with tool radius compensation R0
- ▶ CYCL DEF: Select cycle 4 POCKET MILLING
  - ▶ Set-up clearance: A
  - ▶ Milling depth (depth of the pocket): B
  - ▶ Pecking depth: C
  - ▶ Feed rate for pecking
  - ▶ First side length (length of the pocket, parallel to the first main axis of the working plane): D
  - ▶ Second side length (width of pocket, sign always positive): E
  - ▶ Feed rate
  - ▶ Rotation clockwise: DR-
    - Climb milling with M3: DR+
    - Up-cut milling with M3: DR-
  - ▶ Rounding-off radius R (radius for the pocket corners)

12 CYCL DEF 4.0 POCKET MILLING

13 CYCL DEF 4.1 SET UP2

14 CYCL DEF 4.2 DEPTH-10

15 CYCL DEF 4.3 PECKG4 F80

16 CYCL DEF 4.4 X80



17 CYCL DEF 4.5 Y40

18 CYCL DEF 4.6 F100 DR+ RADIUS 10

19 L Z+100 R0 FMAX M6

20 L X+60 Y+35 FMAX M3



21 L Z+2 FMAX M99



## POCKET FINISHING (212)

- ▶ CYCL DEF: Select Cycle 212 POCKET FINISHING
  - ▶ Set-up clearance: Q200
  - ▶ Depth – Distance between workpiece surface and bottom of hole: Q201
  - ▶ Feed rate for plunging: Q206
  - ▶ Pecking depth: Q202
  - ▶ Feed rate for milling: Q207
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204
  - ▶ Center in 1st axis: Q216
  - ▶ Center in 2nd axis: Q217
  - ▶ First side length: Q218
  - ▶ Second side length: Q219
  - ▶ Corner radius: Q220
  - ▶ Allowance in 1st axis: Q221

The TNC automatically pre-positions the tool in the tool axis and in the working plane. If the depth is greater than or equal to the pecking depth, the tool drills to the depth in one plunge.







## STUD FINISHING (213)

- ▶ CYCL DEF: Select Cycle 213 STUD FINISHING
  - ▶ Set-up clearance: Q200
  - ▶ Depth – Distance between workpiece surface and bottom of hole: Q201
  - ▶ Feed rate for plunging: Q206
  - ▶ Pecking depth: Q202
  - ▶ Feed rate for milling: Q207
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204
  - ▶ Center in 1st axis: Q216
  - ▶ Center in 2nd axis: Q217
  - ▶ First side length: Q218
  - ▶ Second side length: Q219
  - ▶ Corner radius: Q220
  - ▶ Allowance in 1st axs: Q221

The TNC automatically pre-positions the tool in the tool axis and in the working plane. If the depth is greater than or equal to the pecking depth, the tool drills to the depth in one plunge.



# CIRCULAR POCKET MILLING (5)



This cycle requires either a center-cut end mill (ISO 1641) or pilot drilling at pocket center!

- ▶ The tool must be pre-positioned over the center of the slot with tool radius compensation R0
- ▶ CYCL DEF: Select cycle 5
  - ▶ Set-up clearance: A
  - ▶ Milling depth (depth of the pocket): B
  - ▶ Pecking depth: C
  - ▶ Feed rate for pecking
  - ▶ Circle radius R (radius of the pocket)
  - ▶ Feed rate
  - ▶ Rotation clockwise: DR-  
Climb milling with M3: DR+  
Up-cut milling with M3: DR-

17 CYCL DEF 5.0 CIRCULAR POCKET

18 CYCL DEF 5.1 SET UP 2

19 CYCL DEF 5.2 DEPTH -12

20 CYCL DEF 5.3 PECKG 6 F80



21 CYCL DEF 5.4 RADIUS 35

22 CYCL DEF 5.5 F100 DR+

23 L Z+100 R0 FMAX M6

24 L X+60 Y+50 FMAX M3



25 L Z+2 FMAX M99



## CIRCULAR POCKET FINISHING (214)

- ▶ CYCL DEF: Select Cycle 214 CIRCULAR POCKET FINISHING
  - ▶ Set-up clearance: Q200
  - ▶ Depth – Distance between workpiece surface and bottom of hole: Q201
  - ▶ Feed rate for plunging: Q206
  - ▶ Pecking depth: Q202
  - ▶ Feed rate for milling: Q207
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204
  - ▶ Center in 1st axis: Q216
  - ▶ Center in 2nd axis: Q217
  - ▶ Workpiece blank dia.: Q222
  - ▶ Finished part dia.: Q223



The TNC automatically pre-positions the tool in the tool axis and in the working plane. If the depth is greater than or equal to the pecking depth, the tool drills to the depth in one plunge.



## CIRCULAR STUD FINISHING (215)

- ▶ CYCL DEF: Select Cycle 215 CIRCULAR STUD FINISHING
  - ▶ Set-up clearance: Q200
  - ▶ Depth – Distance between workpiece surface and bottom of hole: Q201
  - ▶ Feed rate for plunging: Q206
  - ▶ Pecking depth: Q202
  - ▶ Feed rate for milling: Q207
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204
  - ▶ Center in 1st axis: Q216
  - ▶ Center in 2nd axis: Q217
  - ▶ Workpiece blank dia.: Q222
  - ▶ Finished part dia.: Q223

The TNC automatically pre-positions the tool in the tool axis and in the working plane. If the depth is greater than or equal to the pecking depth, the tool drills to the depth in one plunge.



## SLOT MILLING (3)





- This cycle requires either a center-cut end mill (ISO 1641) or pilot drilling at the starting point!
- The cutter diameter must be smaller than the slot width and larger than half the slot width!

- ▶ The tool must be pre-positioned over the midpoint of the slot and offset by the tool radius with tool radius compensation at R0
- ▶ CYCL DEF: Select cycle 3 SLOT MILLING
  - ▶ Set-up clearance: A
  - ▶ Milling depth (depth of the slot): B
  - ▶ Pecking depth: C
  - ▶ Feed rate for pecking (traverse velocity for plunging)
  - ▶ First side length ? (length of the slot): D
    - The algebraic sign determines the first cutting direction
  - ▶ Second side length ? (width of the slot): E
  - ▶ Feed rate (for milling)

```

10 TOOL DEF 1 L+0 R+6
11 TOOL CALL 1 Z S1500
12 CYCL DEF 3.0 SLOT MILLING
13 CYCL DEF 3.1 SET UP 2
14 CYCL DEF 3.2 DEPTH -15
15 CYCL DEF 3.3 PECKG 5 F80
16 CYCL DEF 3.4 X50
17 CYCL DEF 3.5 Y15
18 CYCL DEF 3.6 F120
19 L Z+100 R0 FMAX M6
20 L X+16 Y+25 R0 FMAX M3
21 L Z+2 M99
    
```



## SLOT WITH RECIPROCATING PLUNGE-CUT (210)





The cutter diameter must be no larger than the width of the slot, and no smaller than one third!

### ► CYCL DEF: Select Cycle 210 SLOT RECIP. PLNG

- Set-up clearance: Q200
- Depth – Distance between workpiece surface and bottom of hole: Q201
- Feed rate for milling: Q207
- Pecking depth: Q202
- Machining operation (0/1/2) – 0 = roughing and finishing, 1 = roughing only, 2 = finishing only: Q215
- Surface coordinate: Q203
- 2nd set-up clearance: Q204
- Center in 1st axis: Q216
- Center in 2nd axis: Q217
- First side length: Q218
- Second side length: Q219
- Angle of rotation (angle by with the slot is rotated): Q224

The TNC automatically pre-positions the tool in the tool axis and in the working plane. During roughing the tool plunges obliquely into the metal in a back-and-forth motion between the ends of the slot. Pilot drilling is therefore unnecessary.





## CIRCULAR SLOT with reciprocating plunge (211)



The cutter diameter must be no larger than the width of the slot, and no smaller than one third!

- ▶ CYCL DEF: Select Cycle 211 CIRCULAR SLOT
  - ▶ Set-up clearance: Q200
  - ▶ Depth – Distance between workpiece surface and bottom of hole: Q201
  - ▶ Feed rate for milling: Q207
  - ▶ Pecking depth: Q202
  - ▶ Machining operation (0/1/2) – 0 = roughing and finishing, 1 = roughing only, 2 = finishing only: Q215
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204
  - ▶ Center in 1st axis: Q216
  - ▶ Center in 2nd axis: Q217
  - ▶ Pitch circlr dia.: Q244
  - ▶ Second side length: Q219
  - ▶ Starting angle of the slot: Q245
  - ▶ Angular length of the slot: Q248

The TNC automatically pre-positions the tool in the tool axis and in the working plane. During roughing the tool plunges obliquely into the metal in a back-and-forth helical motion between the ends of the slot. Pilot drilling is therefore unnecessary.



# Point Patterns



## CIRCULAR PATTERN (220)

- ▶ CYCL DEF: Select Cycle 220 CIRCULAR PATTERN
  - ▶ Center in 1st axis: Q216
  - ▶ Center in 2nd axis: Q217
  - ▶ Angle of rotation: Q244
  - ▶ Starting angle: Q245
  - ▶ Stopping angle: Q246
  - ▶ Stepping angle: Q247
  - ▶ Nr of repetitions: Q241
  - ▶ Set-up clearance: Q200
  - ▶ Surface coordinate: Q203
  - ▶ 2nd set-up clearance: Q204



- Cycle 220 POLAR PATTERN is effective immediately upon definition!
- Cycle 220 automatically calls the last defined fixed cycle!
- Cycle 220 can be combined with Cycles 1, 2, 3, 4, 5, 17, 200, 201, 202, 203, 204, 212, 213, 214, 215
- In combined cycles, the set-up clearance, surface coordinate and 2nd set-up-clearance are always taken from Cycle 220!

The TNC automatically pre-positions the tool in the tool axis and in the working plane.





## LINEAR PATTERN (221)



### ► CYCL DEF: Select Cycle 221 LINEAR PATTERN

- Startng pnt 1st axis: Q225
- Startng pnt 2nd axis: Q226
- Spacing in 1st axis: Q237
- Spacing in 2nd axis: Q238
- Number of columns: Q242
- Number of lines: Q243
- Angle of rotation: Q224
- Set-up clearance: Q200
- Surface coordinate: Q203
- 2nd set-up clearance: Q204



- Cycle 221 LINEAR PATTERN is effective immediately upon definition!
- Cycle 221 automatically calls the last defined fixed cycle!
- Cycle 221 can be combined with Cycles 1, 2, 3, 4, 5, 17, 200, 201, 202, 203, 204, 212, 213, 214, 215
- In combined cycles, the set-up clearance, surface coordinate and 2nd set-up-clearance are always taken from Cycle 221!

The TNC automatically pre-positions the tool in the tool axis and in the working plane.



# SL Cycles

## General Information

SL cycles are useful when you wish to machine a contour consisting of several subcontours (up to 12 islands or pockets).

The subcontours are defined in subprograms.



When working with subcontours, always remember:


- For a pocket the tool machines an inside contour, for an island it is an outside contour!
- Tool approach and departure as well as infeed in the tool axis cannot be programmed in SL cycles!
- Each contour listed in Cycle 14 CONTOUR GEOMETRY must be a closed contour!
- There is a limit to the amount of memory an SL cycle can occupy! A maximum of 128 straight line blocks, for example, can be programmed in an SL cycle.



The contour for cycle 25 CONTOUR TRAIN must not be closed!



Make a graphic test run before actually machining a part. That way you can be sure that you defined the contour correctly!



## CONTOUR GEOMETRY (14)


In Cycle 14 CONTOUR GEOMETRY you list the subprograms that you wish to superimpose to make a complete closed contour.

- ▶ CYCL DEF: Select Cycle 14 CONTOUR GEOMETRY
  - ▶ Label nubers for contour: List the LABEL numbers of the subprograms that you wish to superimpose to make a complete closed contour.



Cycle 14 CONTOUR GEOMETRY is effective immediately upon definition!

```
4 CYCL DEF 14.0 CONTOUR GEOM
5 CYCL DEF 14.1 CONTOUR LABEL 1/2/3
...
36 L Z+200 R0 FMAX M2
37 LBL1
38 L X+0 Y+10 RR
39 L X+20 Y+10
40 CC X+50 Y+50
...
45 LBL0
46 LBL2
...
58 LBL0
```



▲ A and B are pockets, C and D islands



## CONTOUR DATA (20)

Cycle 20 CONTOUR DATA defines the machining information for cycles 21 to 24.

- ▶ CYCL DEF: Select Cycle 20 CONTOUR DATA
  - ▶ Milling depth Q1:
    - Distance from workpiece surface to pocket floor; incremental
  - ▶ Path overlap factor Q2:
    - $Q2 \times \text{tool radius} = \text{stepover factor } k$
  - ▶ Allowance for side Q3:
    - Finishing allowance for the walls of the pocket or island
  - ▶ Allowance for floor Q4:
    - Finishing allowance for the pocket floor
  - ▶ Workpiece surface coordinates Q5:
    - Coordinate of the workpiece surface referenced to the current datum; absolute
  - ▶ Set-up clearance Q6:
    - Distance from the tool to the workpiece surface; incremental
  - ▶ Clearance height Q7:
    - Height at which the tool cannot collide with the workpiece; absolute
  - ▶ Rounding radius Q8:
    - Rounding radius of the tool at inside corners
  - ▶ Direction of rotation Q9:
    - Clockwise  $Q9 = -1$
    - Counter clockwise  $Q9 = +1$




Cycle 20 CONTOUR DATA is effective immediately upon definition!



## PILOT DRILLING (21)


- ▶ CYCL DEF: Select Cycle 21 PILOT DRILLING
  - ▶ Pecking depth Q10; incremental
  - ▶ Feed rate for pecking Q11
  - ▶ Rough mill Q13: Number of the roughing tool



## ROUGH-OUT (22)

The tool moves parallel to the contour at every pecking depth.


- ▶ CYCL DEF: Select Cycle 22 ROUGH-OUT
  - ▶ Pecking depth Q10; incremental
  - ▶ Feed rate for pecking Q11
  - ▶ Feed rate for milling Q12
  - ▶ Coarse roughing tool number Q18
  - ▶ Feed rate for reciprocation Q19



## FLOOR FINISHING (23)

During finishing, the surface is machined parallel to the contour and to the depth previously entered under ALLOWANCE FOR FLOOR.


- ▶ CYCL DEF: Select Cycle 23 FLOOR FINISHING
  - ▶ Feed rate for pecking Q11
  - ▶ Feed rate for milling Q12



## SIDE FINISHING (24)

Finishing the individual contour elements

- ▶ CYCL DEF: Select Cycle 24 SIDE FINISHING
  - ▶ Direction of rotation? Clockwise = -1 Q9:
    - Clockwise Q9 = -1
    - Counterclockwise Q9 = +1
  - ▶ Pecking depth Q10; incremental
  - ▶ Feed rate for pecking Q11
  - ▶ Feed rate for milling Q12
  - ▶ Finishing allowance for side Q14: Allowance for finishing in several passes



- The sum of Q14 + finishing mill radius must be smaller than the sums Q3 (Cycle 20) + roughing tool radius!
- Call Cycle 22 ROUGH-OUT before calling Cycle 24!


## CONTOUR TRAIN (25)

This cycle is for entering data for machining an open contour that has been defined in a contour subprogram.

- ▶ CYCL DEF: Select Cycle 25 CONTOUR TRAIN
  - ▶ Milling depth Q1; incremental
  - ▶ Allowance for side Q3:  
Finishing allowance in the working plane
  - ▶ Workpiece surface coordinates Q5:  
Coordinates referenced to the workpiece datum; absolute
  - ▶ Clearance height Q7:  
Height at which the tool cannot collide with the workpiece; absolute
  - ▶ Pecking depth Q10; incremental
  - ▶ Feed rate for pecking Q11
  - ▶ Feed rate for milling Q12
  - ▶ Climb or up-cut ? Up-cut = -1 Q15
    - Climb milling: Q15 = +1
    - Up-cut milling: Q15 = -1
    - Alternately in reciprocating cuts: Q15 = 0



- Cycle 14 CONTOUR can have only one label number.
- A subprogram can hold no more than 128 line segments.



## CYLINDER SURFACE (27)



This cycle requires a center-cut end mill (ISO 1641)!

Cycle 27 CYLINDER SURFACE enables you to program a cylindrical contour in only two axes, as if in a plane. The TNC then rolls it onto a cylindrical surface.


- ▶ Define a contour in a subprogram and list it in Cycle 14 CONTOUR GEOMETRY
- ▶ CYCL DEF: Select Cycle 27 CYLINDER SURFACE
  - ▶ Milling depth Q1
  - ▶ Finishing allowance for side Q3: Enter the finishing allowance (Either  $Q3 > 0$  or  $Q3 < 0$ )
  - ▶ Set-up clearance ? Q6: Distance from the tool to the workpiece
  - ▶ Pecking depth Q10
  - ▶ Feed rate for pecking Q11
  - ▶ Feed rate for milling Q12
  - ▶ Cylinder radius Q16: Radius of the cylinder
  - ▶ Dimension type? Deg=0 mm/inch=1 Q17: You can enter coordinates in the subprogram in degrees or millimeters




The machine and TNC must be prepared for the CYLINDER SURFACE cycle by the machine tool builder!



- The workpiece must be set up concentrically on the rotary table!
- The tool axis must be perpendicular to the axis of the rotary table!
- Cycle 14 CONTOUR GEOMETRY can have only one label number!
- A subprogram can hold no more than 128 line segments!



▼ The unrolled contour





# Multipass Milling

## RUN DIGITIZED DATA (30)



This cycle requires a center-cut end mill as per ISO 1641!

- ▶ CYCL DEF: Select Cycle 30 RUN DIGITIZED DATA
  - ▶ pgm name for digitized data
  - ▶ MIN. point range
  - ▶ MAX. point range
  - ▶ Set-up clearance: A
  - ▶ Pecking depth: C
  - ▶ Feed rate for pecking: D
  - ▶ Feed rate: B
  - ▶ Miscellaneous function M

```
7 CYCL DEF 30.0 RUN DIGITIZED DATA
```

```
8 CYCL DEF 30.1 PROGRAM1
```



```
9 CYCL DEF 30.2 X+0 Y+0 Z-35
```

```
10 CYCL DEF 30.3 X+250 Y+125 Z+15
```

```
11 CYCL DEF 30.4 SET UP 2
```

```
12 CYCL DEF 30.5 PECKG 5 F125
```

```
13 CYCL DEF 30.6 F350 M112 T0.01 A+10
```





## MULTIPASS MILLING (230)



From the current position, the TNC positions the tool automatically at the starting point of the first machining operation, first in the working plane and then in the tool axis. Pre-position the tool in such a way that there is no danger of collision with the workpiece or fixtures.

### ► CYCL DEF: Select Cycle 230 MULTIPASS MILLING

- Starting point in 1st axis: Q225
- Starting point in 2nd axis: Q226
- Starting point in 3rd axis: Q227
- First side length: Q218
- Second side length: Q219
- Number of cuts: Q240
- Feed rate for plunging: Q206
- Feed rate for milling: Q207
- Stepper feed rate: Q209
- Set-up clearance: Q200





## RULED SURFACE (231)



Starting from the initial position, the TNC positions the tool at the starting point (point 1), first in the working plane and then in the tool axis.

### ► CYCL DEF: Select Cycle 231 RULED SURFACE

- Starting point in 1st axis: Q225
- Starting point in 2nd axis: Q226
- Starting point in 3rd axis: Q227
- 2nd point in 1st axis: Q228
- 2nd point in 2nd axis: Q229
- 2nd point in 3rd axis: Q230
- 3rd point in 1st axis: Q231
- 3rd point in 2nd axis: Q232
- 3rd point in 3rd axis: Q233
- 4th point in 1st axis: Q234
- 4th point in 2nd axis: Q235
- 4th point in 3rd axis: Q236
- Number of cuts: Q240
- Feed rate for milling: Q207




# Cycles for Coordinate Transformation

Cycles for coordinate transformation permit contours to be

• Shifted	Cycle 7 DATUM SHIFT
• Mirrored	Cycle 8 MIRROR IMAGE
• Rotated (in the plane)	Cycle 10 ROTATION
• Tilted out of the plane	Cycle 19 WORKING PLANE
• Enlarged or reduced	Cycle 11 SCALING
	Cycle 26 AXIS-SPECIFIC SCALING

Cycles for coordinate transformation are effective upon definition until they are reset or redefined. The original contour should be defined in a subprogram. Input values can be both absolute and incremental.




## DATUM SHIFT (7)

- CYCL DEF: Select Cycle 7 DATUM SHIFT
  - Enter the coordinates of the new datum or the number of the datum from the datum table.

To cancel a datum shift: Re-enter the cycle definition with the input value 0.

<b>9 CALL LBL1</b>	Call the part subprogram
<b>10 CYCL DEF 7.0 DATUM SHIFT</b>	
<b>11 CYCL DEF 7.1 X+60</b>	
<b>12 CYCL DEF 7.2 Y+40</b>	
<b>13 CALL LBL1</b>	Call the part subprogram



When combining transformations, the datum shift must be programmed before the other transformations!

## MIRROR IMAGE (8)


- CYCL DEF: Select Cycle 8 MIRROR IMAGE
  - Enter the mirror image axis: Either X, Y, or both

To reset the mirror image, re-enter the cycle definition with NO ENT.

```
15 CALL LBL1
16 CYCL DEF 7.0 DATUM SHIFT
17 CYCL DEF 7.1 X+60
18 CYCL DEF 7.2 Y+40
19 CYCL DEF 8.0 MIRROR IMAGE
20 CYCL DEF 8.1 Y
21 CALL LBL1
```



- The tool axis cannot be mirrored!
- The cycle always mirrors the original contour (in this example in subprogram LBL1)!



## Rotation (10)

### ► CYCL DEF: Select Cycle 10 ROTATION

#### ► Enter the rotation angle:


- Input range  $-360^{\circ}$  to  $+360^{\circ}$
- Reference axes for the rotation angle

Working plane	Reference axis and $0^{\circ}$ direction
X/Y	X
Y/Z	Y
Z/X	Z

To reset a ROTATION, re-enter the cycle with the rotation angle 0.

```

12 CALL LBL1
13 CYCL DEF 7.0 DATUM SHIFT
14 CYCL DEF 7.1 X+60
15 CYCL DEF 7.2 Y+40
16 CYCL DEF 10.0 ROTATION
17 CYCL DEF 10.1 ROT+35
18 CALL LBL1
    
```



## WORKING PLANE (19)

Cycle 19 WORKING PLANE supports machining operations with a swivel head and/or tilting table.


- ▶ Call the tool
- ▶ Retract the tool in the tool axis (to prevent collision)
- ▶ Position the rotary axis to the desired angle with an L-block
- ▶ CYCL DEF: Select Cycle 19 WORKING PLANE
  - ▶ Enter the rotary axis and angle
- ▶ Activate compensation: move all the axes
- ▶ Program the contour as if the plane were not tilted

To cancel the WORKING PLANE cycle, re-enter the cycle definition with a 0° angle.



The machine and TNC must be prepared for the WORKING PLANE cycle by the machine tool builder!

```
4 TOOL CALL 1 Z S2500
5 L Z+350 R0 FMAX
6 L B+10 C+90 R0 FMAX
7 CYCL DEF 19.0 WORKING PLANE
8 CYCL DEF 19.1 B+10 C+90
9 L Z+200 R0 F1000
10 L X-50 Y-50 R0
```



## SCALING (11)

- CYCL DEF: Select Cycle 11 SCALING
  - Enter the scaling factor (SCL):
    - Input range 0.000001 to 99.999999:
      - To reduce the contour ...  $SCL < 1$
      - To enlarge the contour ...  $SCL > 1$


To cancel the SCALING, re-enter the cycle definition with SCL1.

```

11 CALL LBL1
12 CYCL DEF 7.0 DATUM SHIFT
13 CYCL DEF 7.1 X+60
14 CYCL DEF 7.2 Y+40
15 CYCL DEF 11.0 SCALING
16 CYCL DEF 11.1 SCL 0.75
17 CALL LBL1
  
```



SCALING can be effective in the working plane only or in all three main axes (depending on machine parameter 7410)!





## AXIS-SPECIFIC SCALING (26)


- ▶ CYCL DEF: Select Cycle 20 AXIS-SPEC. SCALING
  - ▶ Axis and factor: Coordinate axes and factors for extending or compressing contour dimensions
  - ▶ Centerpoint coord. of extention: Center of the extension or compression

To cancel the AXIS-SPEC. SCALING, re-enter the cycle definition assigning the factor 1 to the affected axes.



Coordinate axes sharing coordinates for arcs must be extended or compressed by the same scaling factor!

```
25 CALL LBL1
26 CYCL DEF 26.0 AXIS-SPEC. SCALING
27 CYCL DEF 26.1 X 1.4 Y 0.6 CCX+15 CCY+20
28 CALL LBL1
```



## Special Cycles


### DWELL TIME (9)

The program run is interrupted for the duration of the DWELL TIME.

- ▶ CYCL DEF: Select cycle 9 DWELL TIME
  - ▶ Enter the dwell time in seconds

```
48 CYCL DEF 9.0 DWELL TIME
```

```
49 CYCL DEF 9.1 DWELL 0.5
```



### PGM CALL (12)

- ▶ CYCL DEF: Select cycle 12 PGM CALL
  - ▶ Enter the name of the program that you wish to call




Cycle 12 PGM CALL must be called to become active!

```
7 CYCL DEF 12.0 PGM CALL
```

```
8 CYCL DEF 12.1 LOT31
```

```
9 L X+37.5 Y-12 R0 FMAX M99
```



## Spindle ORIENTATION


- ▶ CYCL DEF: Select cycle 13 ORIENTATION
  - ▶ Enter the orientation angle referenced to the angle reference axis of the working plane:
    - Input range 0 to 360°
    - Input resolution 0.1°
- ▶ Call the cycle with M19



The machine and TNC must be prepared for spindle ORIENTATION by the machine tool builder!

**12 CYCL DEF 13.0 ORIENTATION**

**13 CYCL DEF 13.1 ANGLE 90**



## TOLERANCE (32)



The machine and TNC must be specially prepared for fast contour milling by the machine tool builder.




Cycle 32 is effective as soon as it is defined in the part program!

The TNC automatically smooths the contour between any (compensated or uncompensated) contour elements. The tool therefore moves continuously on the workpiece surface. If necessary, the TNC automatically reduces the programmed feed rate so that the program can be run at the fastest possible speed and without "jolt."

A contour deviation results from the smoothing out. The size of this deviation (tolerance value) is set in a machine parameter by the machine manufacturer. You can change the pre-set tolerance value with Cycle 32 (see figure at top right).

- CYCL DEF: Select Cycle 32 TOLERANCE
  - Tolerance T: permissible contour deviation in mm



# Digitizing 3-D Surfaces



The machine and TNC must be prepared for digitizing by the machine tool builder!

The TNC features the following cycles for digitizing with a measuring touch probe:

- Fix the scanning range: TCH PROBE 5 RANGE  
TCH PROBE 15 RANGE
- Digitize in reciprocating lines: TCH PROBE 16 MEANDER
- Digitize level by level: TCH PROBE 17 CONTOUR LINES
- Digitize in unidirectional lines: TCH PROBE 18 LINE

The digitizing cycles can be programmed only in plain language dialog. They can be programmed for the main axes X, Y and Z as well as for the rotary axes A, B and C.



- Digitizing is not possible while coordinate transformations or a basic rotation is active!
- Digitizing cycles need not be called. They are effective immediately upon definition!

## Selecting digitizing cycles



- Call an overview of touch probe functions

Soft-key directory:



- Select the digitizing cycles



- e.g., select Cycle 15

## Digitizing Cycle RANGE (5)

- ▶ Define the data transmission interface
- ▶ TOUCH PROBE: Select Cycle 5 RANGE
  - ▶ PGM name for digitized data: Enter a name for the NC program in which the digitized data should be stored.
  - ▶ Tch probe axis: Enter the axis of the touch probe
  - ▶ MIN. point range
  - ▶ MAX. point range
  - ▶ Clearance height: Height at which the stylus cannot collide with the model surface:  $Z_s$


**5 TCH PROBE 5.0 RANGE**

**6 TCH PROBE 5.1 PGM NAME: DIGI1**

**7 TCH PROBE 5.2 Z X+0 Y+0 Z+0**

**8 TCH PROBE 5.3 X+100 Y+100 Z+20**

**9 TCH PROBE 5.4 HEIGHT: +100**



## Digitizing Cycle RANGE (15)


- ▶ Define the data transmission interface
- ▶ TOUCH PROBE: Select Cycle 15 RANGE
  - ▶ PGM name for digitized data: Enter a name for the NC program in which the digitized data should be stored.
  - ▶ Tch probe axis: Enter the axis of the touch probe
  - ▶ PGM name for range data: The name of the point table in which the range is defined
  - ▶ MIN point TCH PROBE axis: The minimum point in the touch probe axis
  - ▶ MAX point TCH PROBE axis: The maximum point in the touch probe axis
  - ▶ Clearance height: Height at which the stylus cannot collide with the model surface:  $Z_s$

**5 TCH PROBE 15.0 RANGE**

**6 TCH PROBE 15.1 PGM DIGIT.: DATA**

**7 TCH PROBE 15.2 Z PGM RANGE: TAB1**

**8 TCH PROBE 15.3 MIN:+0 MAX:+35 HEIGHT:+125**




## Digitizing Cycle MEANDER (16)

Cycle 16 MEANDER is for digitizing a 3D contour in a series of back-and-forth line movements.

- ▶ Define Cycle 5 RANGE or 15 RANGE
- ▶ TOUCH PROBE: Select Cycle 16 MEANDER
  - ▶ Line direction: Coordinate axis in whose positive direction the probe moves after touching the first contour point
  - ▶ Scanning angle: Direction of touch probe traverse relative to the axis entered in line direction
  - ▶ Feed rate F: Maximum digitizing feed rate
  - ▶ Min. feed rate: Feed rate for scanning the first line
  - ▶ Min. line spacing: Minimum distance moved forward to start the next line at steep surfaces
  - ▶ Line spacing: Max. distance moved forward to start the next line
  - ▶ Max. probe point interval
  - ▶ Tolerance value: The TNC suppresses the storage of probe points whose distance from a straight line defined by the last two stored points is less than the tolerance value.
  - ▶ Feed rate reduction at edges: Distance at which the TNC begins to reduce the scanning feed rate before steep edges



- The line spacing and max. probe point interval cannot exceed 20 mm!
- Set a line direction that is as perpendicular as possible to steep surfaces!



▲ P: PP.INT = Probe point interval  
L: L.SPAC = Line spacing

**7 TCH PROBE 16.0 MEANDER**

**8 TCH PROBE 16.1 DIRECTN X ANGLE: +0**

**9 TCH PROBE 16.2 F1500FMIN 500MIN.L.SPAC:0.2**

**L.SPAC:0.5 PP.INT:0.5 TOL:0.1 DIST 0.5**



## Digitizing Cycle CONTOUR LINES (17)

Cycle 17 CONTOUR LINES enables you to digitize a 3D surface level by level.

- ▶ Define Cycle 5 RANGE or 15 RANGE
- ▶ TOUCH PROBE: Select Cycle 17 CONTOUR LINES
  - ▶ Time limit: If the touch probe has not orbited the model and returned to the first touch point within this time, the TNC will terminate the cycle. If you do not want a time limit, enter 0.
  - ▶ Starting point: Coordinates of the starting position
  - ▶ Axis and direction of approach: Coordinate axis and direction in which the probe approaches the model
  - ▶ Starting probe axis and direction: Coordinate axis and direction in which the probe begins scanning the model
  - ▶ Feed rate F: Maximum digitizing feed rate
  - ▶ Min. feed rate: Feed rate for scanning the first line
  - ▶ Min. line spacing: Minimum height moved to start the next line at slightly inclined surfaces
  - ▶ Line spacing and direction: Maximum height moved to start the next contour line
  - ▶ Max. probe point interval
  - ▶ Tolerance value: The TNC suppresses the storage of probe points whose distance from a straight line defined by the last two stored points is less than the tolerance value.
  - ▶ Feed rate reduction at edges: Distance at which the TNC begins to reduce the scanning feed rate before steep edges



The line spacing and max. probe point interval cannot exceed 20 mm!


**10 TCH PROBE 17.0 CONTOUR LINES**

**11 TCH PROBE 17.1 TIME: 200 X+50 Y+0**

**12 TCH PROBE 17.2 ORDER Y+/X+**

**13 TCH PROBE 17.3 F1000 FMIN 400MIN.L.SPAC:0.2**

**L.SPAC:0.5 PP.INT:0.5 TOL:0.1 DIST 0.5**



▲ P: PP.INT = Probe point interval  
L: L.SPAC = Line spacing

## Digitizing Cycle LINE (18)

Cycle 18 LINE is for digitizing a 3D surface in lines in one direction. It was developed mainly for digitizing with rotary axes.

- ▶ Define Cycle 5 RANGE or 15 RANGE
- ▶ TOUCH PROBE: Select Cycle 18 LINE
  - ▶ Line direction: Coordinate axis of the digitizing lines.
  - ▶ Scanning angle: Direction of touch probe traverse relative to the axis entered in line direction
  - ▶ Height for feed rate reduction: Coordinate in the tool axis at which at the start of each line the TNC switches from rapid traverse to the probing feed rate.
  - ▶ Feed rate F: Maximum digitizing feed rate
  - ▶ Min. feed rate: Feed rate for scanning the first line
  - ▶ Min. line spacing: Minimum distance moved forward to start the next line at steep surfaces
  - ▶ Line spacing an direction: Maximum distance moved to start the next line
  - ▶ Max. probe point interval
  - ▶ Tolerance value: The TNC suppresses the storage of probe points whose distance from a straight line defined by the last two stored points is less than the tolerance value.
  - ▶ Feed rate reduction at edges: Distance at which the TNC begins to reduce the scanning feed rate before steep edges



The line spacing and max. probe point interval cannot exceed 20 mm!


**10 TCH PROBE 18.0 LINE**

**11 TCH PROBE 18.1 DIRECTN X**

**ANGLE:+0 HEIGHT:+125**

**12 TCH PROBE 18.2 F1000 FMIN 400 IN.L.SPAC:0.2**

**L.SPAC:0.5 PP.INT:0.5 TOL:0.1 DIST 0.5**



# Graphics and Status Displays



See "Graphics and Status Displays"

## Defining the Workpiece in the Graphic Window

The dialog prompt for the BLK-FORM appears automatically whenever you create a new part program.

- ▶ Create a new program or, if you are already in a program, press the soft key BLK FORM
  - ▶ Spindle axis
  - ▶ MIN and MAX point

The following is a selection of frequently needed functions.

## Interactive Programming Graphics



Select the PGM+GRAPHICS screen layout!

The TNC can generate a two-dimensional graphic of the contour while you are programming it:



- ▶ Automatic graphic generation during programming



- ▶ Manually start graphic generation



- ▶ Generate interactive graphics blockwise

Manual operation		Programming and editing					
14 RND R2.5 15 FL AN+0.975 16 FCT DR+ R10.5 CCK+0 CCY+0 17 FLT AN+89.025 18 FCT DR+ R2.5 CLSD- 19 END PGM 35071 MM							
SHOW SOLUTION	SELECT SOLUTION					START SINGLE <input type="checkbox"/>	END SELECT

## Test Graphics and Program Run Graphics



Select the GRAPHICS or PGM+GRAPHICS screen layout!

In the TEST RUN and program run modes the TNC can graphically simulate the machining process. The following display types are available via soft key:




► Plan view



► Projection in three planes



► 3D view



## Status Displays



Select the PGM+STATUS or POSITION+STATUS screen layout!

In the program run modes a window in the lower part of the screen shows information on

- Tool position
- Feed rate
- Active M functions

Further status information is available via soft key for display in an additional window:

STATUS PGM	► Program information
STATUS POS.	► Tool positions
STATUS TOOL	► Tool data
STATUS COORD. TRANSF.	► Coordinate transformations
STATUS TOOL PROBE	► Tool measurement

Program run, full sequence		Programming and editing																				
<pre> 0 BEGIN PGM 3507 MM 1 BLK FORM 0.1 Z X-20 Y-20 Z-20 2 BLK FORM 0.2 X+20 Y+20 Z+0 3 TOOL CALL 1 Z S1000 4 L Z+50 R0 F MAX M3 5 L X+50 Y+50 R0 F MAX M8 6 L Z-5 R0 F MAX 7 CC X+0 Y+0 8 LP PR+14 PA+45 RR F500                     </pre>	<div>DIST.</div> <table> <tr><td>X</td><td>+0.0000</td><td>C</td><td>+0.0000</td></tr> <tr><td>Y</td><td>+0.0000</td><td></td><td></td></tr> <tr><td>Z</td><td>+0.0000</td><td></td><td></td></tr> <tr><td>A</td><td>+0.0000</td><td></td><td></td></tr> <tr><td>B</td><td>+0.0000</td><td></td><td></td></tr> </table>		X	+0.0000	C	+0.0000	Y	+0.0000			Z	+0.0000			A	+0.0000			B	+0.0000		
X	+0.0000	C	+0.0000																			
Y	+0.0000																					
Z	+0.0000																					
A	+0.0000																					
B	+0.0000																					
	<div> A +0.0000 B +180.0000 C +90.0000</div>																					
	<div> Basic rotation +0.0000</div>																					
<div> <div>X</div> <div>-50.0000</div> <div>Y</div> <div>+250.0000</div> <div>Z</div> <div>-150.0000</div> <div>A</div> <div>+0.0000</div> <div>B</div> <div>+180.0000</div> <div>C</div> <div>+90.0000</div> </div>																						
<div>ACTL.  T F 0 M 5/9</div>																						
PAGE ↑	PAGE ↓	<div>BEGIN ↑</div> <div>END ↓</div> <div>RESTORE POS. AT </div> <div>TOOL TABLE</div>																				

## ISO Programming

### Programming Tool Movements with Cartesian Coordinates

G00	Linear motion in rapid traverse
G01	Linear motion
G02	Circular motion, clockwise
G03	Circular motion, counterclockwise
G05	Circular motion without directional data
G06	Circular movement with tangential contour connection
G07*	Paraxial positioning block

### Programming Tool Movements with Polar Coordinates

G10	Linear motion in rapid traverse
G11	Linear motion
G12	Circular motion, clockwise
G13	Circular motion, counterclockwise
G15	Circular motion without directional data
G16	Circular movement with tangential contour connection

\*) Effective blockwise

### Drilling Cycles

G83	Pecking
G200	Drilling
G201	Reaming
G202	Boring
G203	Universal boring
G204	Back boring
G84	Tapping
G85	Rigid tapping (controlled spindle)
G86	Thread cutting

### Pockets, Studs and Slots

G75	Rectangular pocket milling, clockwise machining direction
G76	Rectangular pocket milling, counterclockwise machining direction
G212	Pocket milling
G213	Stud milling
G77	Circular pocket milling, clockwise machining direction
G78	Circular pocket milling, counterclockwise machining direction
G214	Circular pocket finishing
G215	Circular stud finishing
G74	Slot milling
G210	Slot milling with reciprocating plunge
G211	Circular slot

## Point Patterns

- G220 Circular point pattern  
G221 Linear point pattern

## SL Cycles, Group I

- G37 List of contour subprograms  
G56 Pilot drilling  
G57 Rough-out  
G58 Contour milling, clockwise  
G59 Contour milling, counterclockwise

## SL Cycles, Group II

- G37 List of contour subprograms  
G120 Contour data  
G121 Pilot drilling  
G122 Rough-out  
G123 Floor finishing  
G124 Side finishing  
G125 Contour train  
G127 Cylinder surface

## Touch Probe Cycles

- G55\* Measure coordinate  
G400\* Basic rotation over 2 points  
G401\* Basic rotation over 2 holes  
G402\* Basic rotation over 2 studs  
G403\* Basic rotation over a rotary table  
G410\* Datum at center of rectangular pocket  
G411\* Datum at center of rectangular stud  
G412\* Datum at center of hole  
G413\* Datum at center of circular stud  
G414\* Datum at outside corner  
G415\* Datum at outside corner  
G416\* Datum at center of bolt hole circle  
G417\* Datum in touch probe axis  
G418\* Datum at center of 4 holes  
G420\* Measure angle  
G421\* Measure hole  
G422\* Measure circle  
G423\* Measure rectangular pocket  
G424\* Measure rectangular stud  
G425\* Measure slot width  
G426\* Measure ridge width  
G427\* Measure any coordinate  
G430\* Measure bolt hole circle  
G431\* Measure plane

\*) Effective blockwise

### Multipass milling

- G60 Run digitized data
- G230 Multipassmilling
- G231 Ruled surface

### Cycles for Coordinate Transformation

- G53 Datum shift from datum tables
- G54 Entering datum shift directly
- G28 Mirror image
- G73 Rotating the coordinate system
- G72 Scaling factor: enlarging/reducing contours
- G80 Working plane

### Special Cycles

- G04\* Dwell time
- G36 Oriented spindle stop
- G39 Designating a program as a cycle
- G62 Tolerance
- G79\* Cycle call

### Defining the Working Plane

- G17 X/Y working plane, tool axis Z
- G18 Z/X working plane, tool axis Y
- G19 Y/Z working plane, tool axis X
- G20 Fourth axis is tool axis

\*) Effective blockwise

### Chamfer, Rounding, Approach/Departure

- G24\* Chamfer with side length R
- G25\* Corner rounding with radius R
- G26\* Tangential contour approach on an arc with radius R
- G27\* Tangential contour departure on an arc with radius R

### Tool Definition

- G99\* Tool definition in the program with length L and radius R

### Tool Radius Compensation

- G40 No radius compensation
- G41 Radius compensation to the left of the contour
- G42 Radius compensation to the right of the contour
- G43 Paraxial radius compensation: the path is lengthened
- G44 Paraxial radius compensation: the path is shortened

### Dimensional Data

- G90 Absolute dimensions
- G91 Incremental (chain) dimensions



Unit of Measure (at Beginning of Program)	
G70	Inches
G71	Millimeters
Blank Form Definition for Graphics	
G30	Setting the working plane, MIN point coordinates
G31	Dimensional data (with G90, G91), coordinates of the MAX point
Other G functions	
G29	Define last nominal position value as pole
G38	Stopping the program run
G51 *	Calling the next tool (only with central tool file)
G98 *	Setting a label number

Q Parameter Functions	
D00	Assign a value directly
D01	Calculate and assign the sum of two values
D02	Calculate and assign the difference of two values
D03	Calculate and assign the product of two values
D04	Calculate and assign the quotient of two values
D05	Calculate and assign the root from a value
D06	Calculate and assign the sine of an angle in degrees
D07	Calculate and assign the cosine of an angle in degrees
D08	Calculate and assign the square root of the sum of two squares (Pythagorean theorem)
D09	If equal, jump to the given label
D10	If not equal, jump to the given label
D11	If greater than, jump to the given label
D12	If less than, jump to the given label
D13	Find and assign an angle from the arc tangent of two sides or from the sine and cosine of an angle
D14	Output text to screen
D15	Output text or parameter contents through the data interface
D19	Transfer numerical values or Q parameters to the PLC

## Addresses

%	Program beginning	R	Polar coordinate radius with G10/G11/G12/ G13/G15/G16/
A	Swivelling axis around X	R	Circle radius with G02/G03/G05
B	Swivelling axis around Y	R	Corner radius with G25/G26/G27
C	Rotary axis around Z	R	Chamfer length with G24
D	Define Q-parameter functions	R	Tool radius with G99
E	Tolerance for rounding arc with M112	S	Spindle speed in rpm
F	Feed rate in mm/min in positioning blocks	S	Angle for spindle orientation with G36
F	Dwell time in seconds with G04	T	Tool number with G99
F	Scaling factor with G72	T	Tool call
G	G functions (see list of G functions)	T	Call next tool with G51
H	Polar coordinate angle	U	Parallel axis to X
H	Angle of rotation with G73	V	Parallel axis to Y
I	X coordinate of the circle center or pole	W	Parallel axis to Z
J	Y coordinate of the circle center or pole	X	X axis
K	Z coordinate of the circle center or pole	Y	Y axis
L	Label number with G98	Z	Z axis
L	Jump to a label number	*	Character for end of block
L	Tool length with G99		
M	Miscellaneous function		
N	Block number		
P	Cycle parameter for fixed cycles		
P	Value or Q parameter with Q parameter definitions		
Q	Variable Q parameter		

## Miscellaneous Functions M

M00	Stop program run/Stop spindle/Coolant off
M02	Stop program run/Stop spindle/Coolant off Jump back to block 1/Clear status display (depending on machine parameters)
M03	Spindle on clockwise
M04	Spindle on counterclockwise
M05	Stop spindle
M06	Tool change/Stop program run (depending on machine parameters) Stop spindle
M08	Coolant on
M09	Coolant off
M13	Spindle on clockwise/Coolant on
M14	Spindle on counterclockwise/Coolant on
M30	Same function as M02
M89	Vacant miscellaneous function or Cycle call, modally effective (depending on machine parameters)
M90	Constant contour speed at corners (effective only in lag mode)
M91	Within the positioning block: Coordinates are referenced to the machine datum
M92	Within the positioning block: The coordinates are referenced to a position defined by the machine tool builder
M93	Reserved

M94	Reduce rotary axis display to a value below 360°
M95	Reserved
M96	Reserved
M97	Machine small contour steps
M98	Suspend tool path compensation
M99	Cycle call, effective blockwise
M101	Automatic tool change after tool lifetime expires
M102	Reset M101
M103	Reduce the feed rate during plunging to factor F
M105	Machine with first $k_v$ factor
M106	Machine with second $k_v$ factor
M107	See User's Manual
M108	Reset M107
M109	Constant contouring speed of tool cutting edge on arcs (increasing and decreasing the feed rate)
M110	Constant contouring speed of tool cutting edge on arcs (only decreasing the feed rate)
M111	Reset M109/M110
M114	Automatic compensation of machine geometry when working with tilting axes
M115	Reset M114
M116	Feed rate for rotary axes in mm/min

---

M118 <sup>1)</sup>	Superimpose handwheel positioning during program run
M120 <sup>1)</sup>	LOOK AHEAD: Calculate the radius-compensated tool path ahead of time
M126	Permit zero crossover on 360° rotary axes
M127	Cancel M126
M128	Retain position of tool tip when positioning tilting axes (TCPM) <sup>2)</sup>
M129	Reset M128
M130 <sup>1)</sup>	Within the positioning block: points are referenced to the nontilted coordinate system
M134	Exact stop at nontangential contour transitions when positioning with rotary axes
M135	Reset M134
M200 <sup>1)</sup>	Miscellaneous function for laser cutting machines
M204 <sup>1)</sup>	See User's Manual

---

---

<sup>1)</sup> Only with conversational programming

<sup>2)</sup> TCPM: Tool Center Point Management

# HEIDENHAIN

---

## **DR. JOHANNES HEIDENHAIN GmbH**

Dr.-Johannes-Heidenhain-Straße 5

**83301 Traunreut, Germany**

☎ +49 (86 69) 31-0

FAX +49 (86 69) 50 61

E-Mail: [info@heidenhain.de](mailto:info@heidenhain.de)

---

**Technical support** FAX +49 (86 69) 31-1000

E-Mail: [service@heidenhain.de](mailto:service@heidenhain.de)

**Measuring systems** ☎ +49 (86 69) 31-31 04

E-Mail: [service.ms-support@heidenhain.de](mailto:service.ms-support@heidenhain.de)

**TNC support** ☎ +49 (86 69) 31-31 01

E-Mail: [service.nc-support@heidenhain.de](mailto:service.nc-support@heidenhain.de)

**NC programming** ☎ +49 (86 69) 31-31 03

E-Mail: [service.nc-pgm@heidenhain.de](mailto:service.nc-pgm@heidenhain.de)

**PLC programming** ☎ +49 (86 69) 31-31 02

E-Mail: [service.plc@heidenhain.de](mailto:service.plc@heidenhain.de)

**Lathe controls** ☎ +49 (7 11) 95 28 03-0

E-Mail: [service.hsf@heidenhain.de](mailto:service.hsf@heidenhain.de)

---

**[www.heidenhain.de](http://www.heidenhain.de)**