

## Contents: Basic Course G426 ISO Programming



No.	Title	PGM-No.
	<b>Cartesian contour movements</b>	
1	Holes	62151
2	Square	62152
3	Rounding / chamfering corners	62153
4	Contour approach / departure	62154
5	Circular arc with CC, C	62155
6	Tangential contour connection	62156
7	Circular arc with CR	62157
8	Circular arcs	62158
	<b>Polar contour movements</b>	
9	Hexagon (polar)	62159
10	Circle (polar) CP	62160
11	Circular path with tang. connection (polar) CTP	62161
	<b>Canned cycles</b>	
12	Drilling cycle	62170
13	Slot plate	62172
14	Die I	62174
	<b>Program section repeats</b>	
15	Linear hole pattern	62180
16	Hexagon	62181
17	Drilled plate - slanted columns	62182

## Contents: Basic Course G426 ISO Programming

No.	Title	PGM No.
	<b>Subprogramming Technique</b>	
18	Subprogram (groups of holes)	62186
19	Bolt hole circle segments with several tools	62187
20	Milling with several settings	62188
21	Hole pattern	62189
	<b>Contour Cycles</b>	
22	Contour cycles SL II, Roughing out kidney	62190
23	Contour cycles SL II, Kidney-shaped island	62191
	<b>Coordinate transformations</b>	
24	Datum shift and mirror images	62192

Task: **Holes**

Program(s): \_\_\_\_\_  
\_\_\_\_\_



---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

Operating mode "Programming"



Begin program

*%62151 G71*

Define workpiece blank

*G30 ... X... Y... Z...**G31 ... X... Y... Z...*

Define tool

*G99 T... L... R...*

Activate tool

*T... G... S...*

Move to clearance height

*G00 G40 G90 Z+100 M3*

Move to starting point

*X... Y...*

Move to setup clearance

*Z+... M8*

Drill

*G01 Z-... F400*

Retract drill

*G00 Z+2*

Next hole

*X... Y...*

Drill

*G01 Z-...*

Retract drill

*G00 Z+...*

Next hole

*X... Y...*

Drill

*G01 Z-...*


Return to clearance height

*G00 Z+100 M2 (M30)*

End of program

Solution:

## Holes




### Complete program

```
%62151 G71 *
N10 G30 G17 X+0 Y+0 Z-20 *
N20 G31 G90 X+100 Y+100 Z+0 * ..... WORKPIECE BLANK DEFINITIONS
N30 G99 T1 L+0 R+4 * ..... TOOL DEFINITION
N40 T1 G17 S4000 * ..... TOOL CALL
N50 G00 G90 Z+100 M03 * ..... CLEARANCE HEIGHT
N60 X+20 Y+30 * ..... 1ST HOLE
N70 Z+2 M08 *
N80 G01 Z-22 F400 * ..... DRILL
N90 G00 Z+2 *
N100 X+50 Y+70 * ..... 2ND HOLE
N110 G01 Z-22 *
N120 G00 Z+2 *
N130 X+75 Y+30 * ..... 3RD HOLE
N140 G01 Z-22 *
N150 G00 Z+100 M30 *
N999999 %62151 G71 *
```

Task: **Square**

Program(s): \_\_\_\_\_  
\_\_\_\_\_




- Create program
- Define workpiece blank
  
- Define tool
- Activate tool
- Move to clearance height
- Move to auxiliary point G40
- Plunging depth
- Contour starting point G41/G42
- Contour coordinates G41/G42
- ⋮
- Last contour point G41/G42
- Move to auxiliary point G40
- Retract tool, PGM end

```
%62152 G71  
G30 G... X... Y... Z...  
G31 G... X... Y... Z...  
G99 T... L... R...  
T... G... S...  
G00 G40 G90 Z+...  
  
X... Y...  
  
Z-...  
  
G01 G41 X... Y...  
  
X... Y...  
⋮  
X... Y...  
  
G40 X... Y...  
  
G00 Z+... M2/M30
```

Solution:

# Square




## Complete program

```
%62152 G71 *
N10 G30 G17 X+0 Y+0 Z-20 *
N20 G31 G90 X+100 Y+100 Z+0 * ..... WORKPIECE BLANK DEFINITIONS
N30 G99 T1 L+0 R+8 * ..... TOOL DEFINITION
N40 T1 G17 S4000 * ..... TOOL CALL
N50 G00 G40 G90 Z+100 M03 * ..... CLEARANCE HEIGHT
N60 X-30 Y+50 * ..... AUXILIARY POINT (G40)
N70 Z-5 * ..... PLUNGING DEPTH
N80 G01 G41 X+0 Y+50 F400 * ..... CONTOUR STARTING POINT
N90 X+50 Y+100 *
N100 X+100 Y+50 *
N110 X+50 Y+0 *
N120 X+0 Y+50 * ..... LAST CONTOUR POINT
N130 G40 X-30 Y+50 * ..... AUXILIARY POINT
N140 G00 Z+100 M30 * ..... RETRACT TOOL / PGM END
N999999 %62152 G71 *
```

Task: **Rounding / chamfering corners**

Program(s): \_\_\_\_\_  
\_\_\_\_\_



\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_



Solution:

## Rounding / chamfering corners




### Complete program

```

%62153 G71 *
N10 G30 G17 X+0 Y+0 Z-20 *
N20 G31 G90 X+100 Y+100 Z+0 * ..... WORKPIECE BLANK DEFINITION
N30 G99 T1 L+0 R+8 * ..... TOOL DEFINITION
N40 T1 G17 S4000 * ..... TOOL CALL
N50 G00 G40 G90 Z+100 M03 * ..... CLEARANCE HEIGHT
N60 X-30 Y+50 * ..... AUXILIARY POINT (G40)
N70 Z-5 *
N80 G01 G41 X+0 Y+50 F400 * ..... CONTOUR STARTING POINT
N90 X+50 Y+100 *
N100 G25 R10 F200 * ..... ROUND CORNER
N110 X+100 Y+50 *
N120 X+50 Y+0 *
N130 G24 R5 * ..... CHAMFER
N140 X+0 Y+50 *
N150 G40 X-30 Y+50 * ..... AUXILIARY POINT (G40)
N160 G00 Z+100 M30 * ..... PGM END
N999999 %62153 G71 *

```




- Begin program
- Define workpiece blank
- Define tool
- Activate tool
- Move to clearance height
- Move to auxiliary point
- Plunging depth
- First contour point
- Smooth approach
- Contour
- ⋮
- Smooth departure
- Auxiliary point
- Retract tool, PGM end

```

%62154 G71
G30 G... X... Y... Z...
G31 G... X... Y... Z...
G99 T... L... R...
T... G... S...
G00 G40 G90 Z+...
X... Y...
Z-...
G01 G41 X... Y... F...
G26 R...
X... Y...
⋮
G27 R...
G40 X... Y...
G00 Z+... M2/M30
    
```

Solution:

## Contour approach / departure



### Complete program


```

%62154 G71 *
N10 G30 G17 X+0 Y+0 Z-20 *
N20 G31 G90 X+100 Y+100 Z+0 *
N30 G99 T1 L+0 R+8 *
N40 T1 G17 S4000 *
N50 G00 G40 G90 Z+100 M03 *
N60 X-30Y+70* ..... AUXILIARY POINT (G40)
N70 Z-5 *
N80 G01 G41 X+10 Y+70 F400 * ..... STARTING POINT
N80 G26 R3 * ..... SMOOTH APPROCH TO
STARTING POINT

N90 Y+90 *
N100 G25 R10 *
N110 X+50 *
N120 X+90 Y+50 *
N130 Y+10 *
N140 G25 R10 *
N150 X+50 *
N160 X+10 Y+50 *
N170 Y+70* ..... LAST CONTOUR POINT G41
N180 G27 R3 * ..... SMOOTH DEPARTURE TO
AUXILIARY POINT
AUXILIARY POINT

N190 G40 X-30 Y+70 * ..... AUXILIARY POINT
N200 G00 Z+100 M30 *
N999999 %62154 G71 *

```



- Begin program
- Define workpiece blank
- Activate tool
- Move to clearance height
- Move to auxiliary point R0
- Plunging depth
- Approach contour
- Define circle center
- Circular movement
- Depart (aux. point)
- Retract tool, PGM end


```

%62155 G71
G30 G... X... Y... Z...
G31 G... X... Y... Z...
T... G... S...
G00...

G01 G...
I... J...
G02/G03...
G01...
G00...
    
```

Solution:

## Circular arc with CC, C





### Complete program

```
%62155 G71 *
N5 G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15 T3 G17 S2500 * ..... R20
N20 G00 G40 G90 Z+100 M03 *
N25 X-30 Y+50 * ..... AUXILIARY POINT
N30 Z-5 *
N35 G01 G41 X-5 Y+20 F250 *
N40 X+23,542 Y+20 *
N45 I+50 J+50 * ..... CIRCLE CENTER
N50 G03 X+23,542 Y+80 * ..... CIRCULAR MOVEMENT
N55 G01 X-5 *
N60 G40 X-30 Y+50 *
N65 G00 Z+100 M30 *
N999999 %62155 G71 *
```

Task: **Tangential contour connection  
(cartesian)**

Program(s): \_\_\_\_\_  
\_\_\_\_\_



---

---

---

---

---

---

---

---

---

---

---

---

---


---

---

---

Solution:

## Tangential contour connection (cartesian)




### Complete program

```
%62156 G71 *
N5  G30 G17 X+0 Y+0 Z-20 *
N10  G31 G90 X+100 Y+100 Z+0 *
N15  T11 G17 S2500 * ..... R10
N20  G00 G40 G90 Z+100 M03 * ..... CLEARANCE HEIGHT
N25  X+45 Y-25 * ..... AUXILIARY POINT
N30  Z-5 *
N35  G01 G42 X+20 Y-3 F250 * ..... CONTOUR STARTING POINT
N40  Y+30 *
N45  G06 X+70 Y+60 * ..... TANGENTIAL CIRCULAR PATH
N50  G01 X+103 *
N55  G40 X+110 Y+50 F500 *
N60  G00 Z+100 M30 *
N999999 %62156 G71 *
```

Task: **Circular arc with CR**


Program(s): \_\_\_\_\_  
\_\_\_\_\_





Solution:

## Circular arc with CR




### Complete program

```
%62157 G71 *
N5 G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15 T13 G17 S2500 * ..... R20
N20 G00 G40 G90 Z+100 M03 *
N25 X-30 Y-30 * ..... AUXILIARY POINT
N30 Z-5 *
N35 G01 G41 X+10 Y-3 F250 * ..... APPROACH STARTING POINT
N40 Y+50 *
N45 G02 X+90 Y+50 R+80 * ..... CIRCULAR ARC
N50 G01 Y-3 *
N55 G40 X+110 Y-30 F500 * ..... DEPART (AUXILIARY POINT)
N60 G00 Z+100 M30 *
N999999 %62157 G71 *
```

Task: **Circular arcs**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_



Point	X	Y
P <sub>1</sub>	6.645	35.495
P <sub>2</sub>	55.505	69.488

Point	X	Y
P <sub>3</sub>	58.995	30.025
P <sub>4</sub>	19.732	21.191

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_



Task: **Hexagon (polar)**

Program(s): \_\_\_\_\_  
\_\_\_\_\_




Begin program  
Define workpiece blank  
  
Activate tool  
Move to clearance height  
Define pole  
Auxiliary point in polar coord.  
Plunging depth  
First contour point  
Approach tangentially  
Contour  
⋮  
Depart tangentially  
Retract tool, PGM end

```
%62159 G71  
G30 G... X... Y... Z...  
G31 G... X... Y... Z...  
T... G... S...  
G00 Z...  
I... J...  
G10 R... H...  
G00 Z...  
G11 ...  
G26 R...  
G11 ...  
⋮  
G27 R...  
G00 Z...
```

Solution:

## Hexagon (polar)




### Complete program

```
%62159 G71 *
N5 G30 G17 X-50 Y-50 Z-20 *
N10 G31 G90 X+50 Y+50 Z+0 *
N15 T13 G17 S2500 * ..... R20
N20 G00 G40 G90 Z+100 M03 *
N25 H+0 J+0 * ..... POLE
N30 G10 R+80 H+0 * ..... POLAR AUXILIARY POINT
N35 Z-5 *
N40 G11 G42 H+0 R+40 F250 * ..... APPROACH STARTING POINT OF
N40 G26 R4 * ..... CONTOUR TANGENTIALLY
N45 G11 H+60 *
N50 H+120 *
N55 H+180 *
N60 H+240 *
N65 H+300 *
N70 H+0 *
N75 G27 R4 * ..... DEPART TANGENTIALLY
N80 G11 G40 H+0 R+80 * ..... POLAR AUXILIARY POINT
N85 G00 Z+100 M30 *
N999999 %62159 G71 *
```

Task: **Circle (polar) CP**

Program(s): \_\_\_\_\_  
\_\_\_\_\_



Begin program

Define workpiece blank

Activate tool

Move to clearance height

Define pole

Auxiliary point in polar coord.


Contour

Auxiliary point

Retract tool, PGM end

Solution:

## Circle (polar) CP



### Complete program


```

%62160 G71 *
N5  G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15  T13 G17 S2500 * ..... R20
N20  G00 G40 G90 Z+100 M03 *
N25  I+50 J+50 * ..... POLE
N30  G10 R+80 H+180 * ..... AUXILIARY POINT
N35  G00 Z-5 *
N40  G11 G41 R+40 H+180 F250 * ..... APPROACH STARTING POINT OF
N45  G26 R3 * ..... CONTOUR TANGENTIALLY
N50  G12 G91 H+360 * ..... CIRCULAR PATH (POLAR)
N55  G27 R3 * ..... DEPART TANGENTIALLY
N60  G11 G40 G90 H+180 R+80 *
N65  G00 Z+100 M30 *
N999999 %62160 G71 *

```

Task: **Circular path with tangential connection (polar) CTP**

Program(s): \_\_\_\_\_  
\_\_\_\_\_



Begin program  
Define workpiece blank

Activate tool  
Move to clearance height

Define pole

Auxiliary point

Contour


Auxiliary point

Retract tool, PGM end



Solution:

## Circular path with tangential connection (polar) CTP



### Complete program


```

%62161 G71 *
N5  G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15  T13 G17 S4000 * ..... R20
N20  G00 G40 G90 Z+100 M03 *
N25  X-30 Y-30 * ..... AUXILIARY POINT
N30  Z-5 *
N35  G01 G41 X+0 Y+0 F250 * ..... APPROACH STARTING POINT OF
N40  G26 R3 * ..... CONTOUR TANGENTIALLY
N45  G01 Y+30 *
N50  X+40 Y+60 *
N55  I+20 J+20 * ..... POLE
N60  G16 H+23,199 R+76,158 * ..... TANGENTIAL CIRC.PATH(POLAR)
N65  G01 X+90 Y+0 *
N70  G40 X+110 Y+10 * ..... DEPART
N75  G00 Z+100 M30 *
N999999 %62161 G71 *

```

Task: **Drilling cycle**

Program(s): \_\_\_\_\_  
\_\_\_\_\_



Begin program

Define workpiece blank

Activate tool

Define cycle

Move to clearance height

Starting point 1st hole / cycle call


2nd hole / cycle call

3rd hole / cycle call

Retract tool, PGM end

Solution:

## Drilling cycle





### Complete program

```

%62170 G71 *
N5 G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15 T7 G17 S1000 * ..... R4
N20 G20
    Q200=2 ..... SETUP CLEARANCE
    Q201=23 ..... DEPTH
    Q206=150 ..... FEED RATE FOR PLUNGING
    Q202=5 ..... PLUNGING DEPTH
    Q210=0 ..... DWELL TIME AT TOP
    Q203=+0 ..... SURFACE COORDINATE
    Q204=2 ..... 2ND SETUP CLEARANCE
    Q211=0 * ..... DWELL TIME AT DEPTH
N25 G00 G40 G90 Z+100 M03 *
N30 G00 X+20 Y+30 M99 * ..... STARTING POSITION
N35 G00 X+50 Y+70 M99 * ..... 2ND HOLE
N40 G00 X+75 Y+30 M99 * ..... 3RD HOLE
N45 G00 Z+100 M30 *
N999999 %62170 G71 *
    
```

Task: **Slot plate**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_




---



---



---



---



---



---



---



---



---



---




---



---

Solution:

## Slot plate



### Complete program

```

%62172 G71 *
N5 G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15 T8 G17 S1000 *

N20 G00 G40 G90 Z+100 M03 *
N25 G210
Q200=2 ..... SETUP CLEARANCE
Q201=-10 ..... DEPTH
Q207=100 ..... FEED RATE FOR MILLING
Q202=5 ..... PLUNGING DEPTH
Q215=0 ..... MACHINING OPERATION
Q203=+0 ..... SURFACE COORDINATE
Q204=2 ..... 2ND SETUP CLEARANCE
Q216=+50 ..... CENTER IN 1ST AXIS
Q217=+25 ..... CENTER IN 2ND AXIS
Q218=75 ..... 1ST SIDE LENGTH
Q219=15 ..... 2ND SIDE LENGTH
Q224=+20 ..... ANGLE OF ROTATION
Q338=5* ..... INFEEED FOR FINISHING
N30 M99*


N35 G211
Q200=2 ..... SETUP CLEARANCE
Q201=-10 ..... DEPTH
Q207=100 ..... FEED RATE FOR MILLING
Q202=5 ..... PLUNGING DEPTH
Q215=0 ..... MACHINING OPERATION
Q203=+0 ..... SURFACE COORDINATE
Q204=2 ..... 2ND SETUP CLEARANCE
Q216=+40 ..... CENTER IN 1ST AXIS
Q217=+60 ..... CENTER IN 2ND AXIS
Q244=50 ..... PITCH CIRCLE DIAMETER
Q219=12 ..... 2ND SIDE LENGTH
Q245=+35 ..... STARTING ANGLE
Q248=180 ..... ANGULAR LENGTH
Q338=5* ..... INFEEED FOR FINISHING
N40 M99 *

N45 G00 Z+100 M30 *
N999999 %62172 G71 *

```

Task: **Die I**

Program(s): \_\_\_\_\_  
\_\_\_\_\_



\_\_\_\_\_

\_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Complete program

```

%62174 G71 *
N5 G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15 T13 G17 S800 *
N20 G00 G40 G90 Z+100 M03 *
N25 G215 ..... FINISH CYLINDRICAL STUD
    Q200=2 ..... SETUP CLEARANCE
    Q201=10 ..... DEPTH
    Q206=150 ..... FEED RATE FOR PLUNGING
    Q202=10 ..... PLUNGING DEPTH
    Q207=200 ..... FEED RATE FOR MILLING
    Q203=+0 ..... SURFACE COORDINATE
    Q204=50 ..... 2ND SETUP CLEARANCE
    Q216=+50 ..... CENTER IN 1ST AXIS
    Q217=+50 ..... CENTER IN 2ND AXIS
    Q222=140 ..... WORKPIECE BLANK DIAMETER
    Q223=101* ..... FINISHED PART DIAMETER

N30 M99*
N35 T7 DR+1 G17 S2000 *
N40 G00 G40 G90 Z+100 M03 *
N45 G75 ..... POCKET MILLING
    P01 2 ..... SETUP CLEARANCE
    P02 -5 ..... DEPTH
    P03 5 ..... PLUNGING DEPTH
    P04 100 ..... FEED RATE FOR PLUNGING
    P05 X+60 ..... LENGTH IN X
    P06 Y+30 ..... LENGTH IN Y
    P07 250 ..... FEED RATE FOR MILLING
    P087 *

N50 G00 X+50 Y+50 *
N55 Z+2 M99 *
N60 Z+100 M06*
    
```

```



N65 T8 G17 S1000 *
N70 G00 G40 G90 Z+100 M03 *
N75 G212 ..... POCKET FINISHING
    Q200=2 ..... SETUP CLEARANCE
    Q201=5 ..... DEPTH
    Q206=250 ..... FEED RATE FOR PLUNGING
    Q202=5 ..... PLUNGING DEPTH
    Q207=250 ..... FEED RATE FOR MILLING
    Q203=+0 ..... SURFACE COORDINATE
    Q204=20 ..... 2ND SETUP CLEARANCE
    Q216=+50 ..... CENTER IN 1ST AXIS
    Q217=+50 ..... CENTER IN 2ND AXIS
    Q218=60 ..... 1ST SIDE LENGTH
    Q219=30 ..... 2ND SIDE LENGTH
    Q220=5,25 ..... CORNER RADIUS
    Q221=0* ..... ALLOWANCE
N80 M99 *
N85 G215 ..... FINISH CYLINDRICAL STUD
    Q200=2 ..... SETUP CLEARANCE
    Q201=-10 ..... DEPTH
    Q206=250 ..... FEED RATE FOR PLUNGING
    Q202=10 ..... PLUNGING DEPTH
    Q207=250 ..... FEED RATE FOR MILLING
    Q203=+0 ..... SURFACE COORDINATE
    Q204=20 ..... 2ND SETUP CLEARANCE
    Q216=+50 ..... CENTER IN 1ST AXIS
    Q217=+50 ..... CENTER IN 2ND AXIS
    Q222=92 ..... WORKPIECE BLANK DIAMETER
    Q223=90* ..... FINISHED PART DIAMETER
N90 M99 *
N95 G00 Z+100 M30 *
N999999 %62174 G71 *

```



Task: **Program section repeats - linear hole pattern**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_




Begin program  
 Define workpiece blank  
  
 Activate tool  
  
 Define cycle  
 Move to clearance height  
  
 Move to pre-position  
  
**Define label**  
  
 Traverse movement/  
 cycle call  
  
**Label call**  
  
 Retract tool, PGM end

<i>%62180 G71</i>
<i>G30 G... X... Y... Z...</i>
<i>G31 G... X... Y... Z...</i>
<i>T... G... S...</i>
<i>G200...</i>
<i>G00 G40 G90 Z...</i>
<i>X... Y...</i>
<i>G98 L...</i>
<i>G00 G91 X... M99</i>
<i>L... /...</i>
<i>...</i>

Solution:

## Program section repeats - linear hole pattern




### Complete program

```
%62180 G71 *
N5  G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+50 Z+0 *
N15  T1 G17 S4000 *
N20  G00 G40 G90 Z+100 M03 *
N25  G200
      Q200=2 ..... SETUP CLEARANCE
      Q201=-20 ..... DEPTH
      Q206=150 ..... FEED RATE FOR PLUNGING
      Q202=4 ..... PLUNGING DEPTH
      Q210=0 ..... DWELL TIME AT TOP
      Q203=+0 ..... SURFACE COORDINATE
      Q204=2 ..... 2ND SETUP CLEARANCE
      Q211=0* ..... DWELL TIME AT BOTTOM
N30  G00 X+5 Y+30 * ..... STARTING POSITION
N35  G98 L1* ..... DEFINE LABEL
N40  G00 G91 X+10 M99 *
N45  L1,7* ..... LABEL CALL WITH REPEATS
N50  G00 Z+100 M30 *
N999999 %62180 G71 *
```

Task: **Hexagon**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_



Program layout:

**Conventional preparations:**

*G30/G31*

Define workp. blank

Activate tool  
 Starting position

*T...  
 G00 G40 G90...*

Pole  
 Auxiliary point

Approach contour

*I... J...  
 G10 R... H...  
 G00 Z...  
 G11.../G26 R...*

Infeed  
 1st contour point

Define label

*G98 L...*

Traverse movement

*G11 G91 H...*

Label call

*L.../...*

Retract tool

*G11 G40 G90 H...*


Auxiliary point

**End**

*G00 Z...*

Solution:

## Hexagon





### Complete program

```
%62181 G71 *
N5 G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15 T12 G17 S2000 * ..... R15
N20 G00 G40 G90 Z+100 M03 *
N25 I+50 J+50 * ..... POLE
N30 G10 R+80 H+0 * ..... AUXILIARY POINT
N35 G00 Z-5 *
N40 G11 G41 R+40 F250 * ..... CONTOUR STARTING POINT
N45 G25 R3 *
N50 G98 L1 * ..... DEFINE LABEL
N55 G11 G91 H-60 *
N60 L1,4 * ..... LABEL CALL WITH REPEATS
N65 G11 G91 H-60 *
N65 G26 R3 *
N70 G11 G40 G90 H+0 R+80 * ..... AUXILIARY POINT
N75 G00 Z+100 M30 *
N999999 %62181 G71 *
```

**Task: Drilled plate - slanted columns**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_




---



---



---



---



---



---



---



---



---



---



---



---




---



---

**Move up and down columns (meandering)**




**Drilling pattern**

<i>G00 X... Y...</i>	Absolut pre-position
<i>G98 L 1</i>	Define label 1
<i>G91 X... M99</i>	Cross over to 1st hole
<i>G98 L 2</i>	Define label 2
<i>X... Y... M99</i>	Move up the column
<i>L 2,...</i>	Cross over to 2nd column
<i>X... M99</i>	
<i>G98 L 3</i>	Define label 3
<i>X... Y... M99</i>	Move down the column
<i>L 3,...</i>	Remaining groups
<i>L 1,...</i>	

Solution:

## Drilled plate - slanted columns



### MAIN PROGRAM


```

%62182 G71 *
N5  G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15  T5 G17 S4000 * ..... R2:5
N20  G00 G40 G90 Z+100 M03 *
N25  G200 ..... DRILLING
      Q200=2 ..... SETUP CLEARANCE
      Q201=15 ..... DEPTH
      Q206=250 ..... FEED RATE FOR PLUNGING
      Q202=8 ..... PLUNGING DEPTH
      Q210=0 ..... DWELL TIME AT TOP
      Q203=+0 ..... SURFACE COORDINATE
      Q204=20 ..... 2ND SETUP CLEARANCE
      Q211=0 * ..... DWELL TIME AT DEPTH
N30  G00 X-10 Y+10 *
N35  G98 L1 *
N40  G00 G91 X+20 M99 *
N45  G98 L2 *
N50  G00 X+3 Y+15 M99 *
N55  L2,4 *
N60  G00 X+10 M99 *
N65  G98 L3 *
N70  G00 X-3 Y-15 M99 *
N75  L3,4 *
N80  L1,2 *
N85  G00 G90 Z+100 M30 *
N999999 %62182 G71 *

```

Task: **Subprogram (group of holes)**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_



**Begin program**

<code>%... G71</code>	
<code>•</code>	
<code>•</code>	
<code>T...</code>	Activate tool
<code>G...</code>	Define cycle
<code>G00 Z+...</code>	Move to clear. height
<code>G00 X... Y...</code>	Start. pos. hole group①
<code>L...,...</code>	Call SPGM
<code>G00 X... Y...</code>	Start. pos. hole group②
<code>L...,...</code>	Call SPGM
<code>G00 X... Y...</code>	Start. pos. hole group③
<code>L...,...</code>	Call SPGM

**Retract tool, end**

`G00 G40 Z+100 M2`

**SPGM**


<code>G98 L...</code>	
<code>G98 L 0</code>	

**SPGM end**



Solution:

## Subprogram (group of holes)



## MAIN PROGRAM

```

%62186 G71 *
N10 G30 G17 X+0 Y-70 Z-20 *
N20 G31 G90 X+100 Y+0 Z+0 *
N30 T4 G17 S2000 * ..... TOOL CALL, R2
N40 G20 ..... DRILLING
      Q200=2 ..... SETUP CLEARANCE
      Q201=18 ..... DEPTH
      Q206=150 ..... FEED RATE FOR PLUNGING
      Q202=7 ..... PLUNGING DEPTH
      Q210=0 ..... DWELL TIME ON TOP
      Q203=+0 ..... SURFACE COORDINATE
      Q204=50 ..... 2ND SETUP CLEARANCE.
      Q211=0* ..... DWELL TIME AT BOTTOM
N50 G00 G40 G90 Z+100 M03 * ..... CLEARANCE HEIGHT
N60 X+20 Y-10 * ..... STARTING POINT HOLE GROUP①
N70 L1,0* ..... CALLSPGM

N80 G00 X+63 Y-12 * ..... STARTING POINT HOLE GROUP②
N90 L1,0* ..... CALLSPGM

N100 G00 X+42 Y-32 * ..... STARTING POINT HOLE GROUP③
N110 L1,0* ..... CALLSPGM

Retract tool, end N120 G00 G40 G90 Z+100 M30 *
  
```

## SPGM


```

N130 G98 L1 *
N140 M99 *
N150 G00 G91 X+15 M99 *
N160 G00 Y-15 M99* ..... DRILLING PATTERN
N170 G00 X-15 M99 *
N180 G90 *
N190 G98 L0 *
N999999 %62186 G71 *
  
```

## SPGM, END

**Task: Bolt hole circle segments with several tools**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_




---



---



---



---



---



---



---



---



---



---



---



---

Program layout:

## Nesting for double bolt-hole circles

**Conventional preparations:**

*G30/G31*

**Centering**

*T...*  
*G200.../G00 Z+100*

*L 1,0*

**Drilling**

*T...*  
*G...*

*L 1,0*

**Tapping**

*T...*  
*G...*

*L 1,0*

**Retract tool, end**

*G00 Z100 M2*

**SPGM1**

*G98 L 1*

*I...J...*

*L 2,0*

*I...J...*

*L 2,0*

*G98 L 0*

Circle center left

Call bolt-hole circle segm.

Circle center right

Call bolt-hole circle segm.

**End of SPGM1**

**SPGM2, bolt-hole circle segm.**

*G98 L 2*

*G10 R... H... M3*  
*G00 Z+2 M99*

Starting position

*G98 L 3*

■

Remaining holes

*L 3,...*

**Partial repeats**

*LP PR... PA...*

*G98 L 4*

■


*L 4,...*

**End of SPGM2**

*G98 L 0*

Solution:

## Bolt hole circle segments with several tools



### MAIN PROGRAM

```

%62187 G71 *
N10 G30 G17 X+0 Y+0 Z-20 *
N20 G31 G90 X+150 Y+60 Z+0 *
N30 T4 G17 S2500 * ..... R2
N40 G00 G40 G90 Z+100 M03 *
N50 G200 ..... CIRCLE CENTER
    Q200=2 ..... SETUP CLEARANCE
    Q201=-3,2 ..... DEPTH
    Q206=150 ..... FEED RATE FOR PLUNGING
    Q202=3,2 ..... PLUNGING DEPTH
    Q210=0 ..... DWELL TIME AT TOP
    Q203=+0 ..... SURFACE COORDINATE
    Q204=2 ..... 2ND SETUP CLEARANCE
    Q211=0* ..... DWELL TIME AT BOTTOM
N60 L1,0 *

N70 G00 Z+100 M06 *
N80 T5 G17 S2000 * ..... R2.5
N90 G00 G40 G90 Z+100 M03 *
N100 G203 ..... UNIVERSAL DRILLING
    Q200=2 ..... SETUP CLEARANCE
    Q201=15 ..... DEPTH
    Q206=150 ..... FEED RATE FOR PLUNGING
    Q202=5 ..... PLUNGING DEPTH
    Q210=0 ..... DWELL TIME AT TOP
    Q203=+0 ..... SURFACE COORDINATE
    Q204=2 ..... 2ND SETUP CLEARANCE
    Q212=1 ..... DECUREMENT
    Q213=0 ..... NUMBER OF CHIP BREAKINGS
    Q205=3 ..... MIN. PLUNGING DEPTH
    Q211=0 ..... DWELL TIME AT BOTTOM
    Q208=30000 ..... RETRACTION FEED RATE
    Q256=0,2* ..... CHIP BREAKING RETRACTION
N110 L1,0*

N120 G00 G90 Z+100 M06 *
N130 T6 G17 S300 * ..... R3
N140 G00 G40 G90 Z+100 M03 *
N150 G84 ..... TAPPING
    P01 5
    P02 -15
    P03 0
    P04 300 *
N160 L1,0 *
N170 G00 G40 G90 Z+100 M30 *

```

Solution:

## Bolt hole circle segments with several tools

### SPGM



*N180 G98 L1\**  
*N190 I+40 J+0 \**  
*N200 L2,0 \**  
*N210 I+110 J+0 \**  
*N220 L2,0 \**  
*N230 G98 L0 \**

*N240 G98 L2 \**  
*N250 G10 G90 R+55 H+120 \**  
*N260 G00 Z+5 M99 \**  
*N270 G98 L3 \**  
*N280 G10 G91 R-10 M99 \**  
*N290 L3,3 \**  
*N300 G10 G90 R+15 H+60 M99 \**  
*N310 G98 L4 \**  
*N320 G10 G91 R+10 M99 \**  
*N330 L4,3 \**  
*N340 G90 \**  
*N340 G98 L0 \**

*N999999 %62187 G71 \**

Task: **Milling with several settings**

Program(s): \_\_\_\_\_  
\_\_\_\_\_



---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

Program layout:

## Milling with several tools and settings

**Conventional preparations:**

*G30/G31*

Workpiece blank

**Roughing**

```
T...  
G00 G40 G90 X... Y...  
Z0 M3
```

Tool call  
Starting position

```
G98 L 2
```

```
G91 Z-5
```

```
L 1,0
```

```
L 2,...
```

SPGM call

```
G00 Z+100 M6
```

Tool exchange

**Finishing**

```
T...  
G00 G40 X... Y...  
Z-30 M3
```

Tool call  
Starting position

```
L 1,0
```

SPGM call

**Retract tool, end**

```
G00 Z100 M2
```

**SPGM, contour**


```
G98 L 1
```

```
•  
•  
•  
•  
•
```

```
G98 L 0
```

Solution:

## Milling with several settings



### MAIN PROGRAM

```

%62188 G71 *
N10 G30 G17 X+0 Y+0 Z-40 *
N20 G31 G90 X+100 Y+100 Z+0 *
N30 T13 G17 S2000 * ..... R20
N40 G00 G40 G90 Z+100 M03 *
N50 X-30 Y+70 * ..... AUXILIARY POINT
N60 Z+0 *

N70 G98 L2 *
N80 G01 G91 Z-5 F200 * ..... SETTING
N90 L1,0 * ..... CALL CONTOUR
N100 L2,5 * ..... FURTHER CONTOUR SECTIONS

N110 G00 Z+100 M06 *
N120 T14 G17 S3000 *
N130 G00 G40 G90 Z+100 M03 *
N140 X-30 Y+70 *
N150 G01 Z-30 F500 *
N160 L1,0 *
N170 G00 Z+100 M30 *
    
```

Retract tool, end

### SPGM, contour

```



N180 G98 L1 *
N190 G01 G41 G90 X+10 Y+70 F200 *
N190 G26 R3 *
N200 X+10 Y+90 *
N210 G25 R10 *
N220 G01 X+50 Y+90 *
N230 G25 R20 *
N240 G01 X+90 Y+50 *
N250 G25 R20 * ..... CONTOUR
N260 G01 X+90 Y+10 *
N270 G25 R10 *
N280 G01 X+50 *
N290 G25 R20 *
N300 G01 X+10 Y+50 *
N310 G25 R20 *
N320 G01 Y+70 *
N330 G27 R3 *
N340 G01 G40 X-20 Y+70 *
N350 G98 L0 *
N999999 %62188 G71 *
    
```

### SPGM end



Task: **Hole pattern**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_




---



---



---



---



---



---



---



---



---



---



---



---




---



---

Solution:

## Hole pattern



## MAIN PROGRAM

```

%62189 G71 *
N5  G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15  T4 G17 S1500 * ..... R2
N20  G00 G40 G90 Z+100 M03 *
N25  G200 ..... CENTER
      Q200=2 ..... SETUP CLEARANCE
      Q201=-3,5 ..... DEPTH
      Q206=150 ..... FEED RATE FOR PLUNGING
      Q202=3,5 ..... PLUNGING DEPTH
      Q210=0 ..... DWELL TIME AT TOP
      Q203=+0 ..... SURFACE COORDINATE
      Q204=2 ..... 2ND SETUP CLEARANCE
      Q211=0 * ..... DWELL TIME AT DEPTH
N30  L1,0 *
N35  L2,0 *
N40  G00 Z+100 M06 *

N45  T5 G17 S1500 * ..... R2
N50  D00 Q201 P01-17 * ..... DEPTH
N55  D00 Q202 P01+6 * ..... PLUNGING DEPTH
N60  G00 G40 G90 Z+100 M03 *
N65  L1,0 *
N70  L2,0 *
N75  G00 Z+100 M06 *

N80  T6 G17 S300 *
N85  G85 ..... RIGID TAPPING
      P01 2 ..... SETUP CLEARANCE
      P02-14 ..... DEPTH
      P03+1 * ..... PITCH
N90  G00 G40 G90 Z+100 M03 *
N95  L1,0 *
N100 L2,0 *
N105 G00 Z+100 M30 *

```

Retract tool, end

Solution:


## Hole pattern

### SPGM

<i>N110 G98 L1 *</i>	
<i>N115 G220</i> .....	POLAR PATTERN
<i>Q216=+90</i> .....	CENTER IN 1ST AXIS
<i>Q217=+10</i> .....	CENTER IN 2ND AXIS
<i>Q244=100</i> .....	PITCH CIRCLE DIAMETER
<i>Q245=+90</i> .....	STARTING ANGLE
<i>Q246=+180</i> .....	STOPPING ANGLE
<i>Q247=+15</i> .....	STEPPING ANGLE
<i>Q241=7</i> .....	NUMBER OF REPETITIONS
<i>Q200=2</i> .....	SETUP CLEARANCE
<i>Q203=+0</i> .....	SURFACE COORDINATE
<i>Q204=2</i> .....	2ND SETUP CLEARANCE
<i>Q301=1 *</i> .....	MOVE TO CLEARANCE
<i>N120 G98 L0 *</i>	
<i>N125 G98 L2 *</i>	
<i>N130 G221</i> .....	CARTESIAN PATTERN
<i>Q225=+30</i> .....	STARTING POINT IN 1ST AXIS
<i>Q226=+30</i> .....	STARTING POINT IN 2ND AXIS
<i>Q237=+15</i> .....	SPACING IN 1ST AXIS
<i>Q238=+20</i> .....	SPACING IN 2ND AXIS
<i>Q242=5</i> .....	NUMBER OF COLUMNS
<i>Q243=2</i> .....	NUMBER OF LINES
<i>Q224=+80</i> .....	ANGLE OF ROTATION
<i>Q200=2</i> .....	SETUP CLEARANCE
<i>Q203=+0</i> .....	SURFACE COORDINATE
<i>Q204=2</i> .....	2ND SETUP CLEARANCE
<i>Q301=1 *</i> .....	MOVE TO CLEARANCE
<i>N135 G98 L0 *</i>	
<i>N999999 %62189 G71 *</i>	

**Task: Contour cycles SL II, Roughing out kidney**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_



Point	X	Y
P <sub>1</sub>	6.645	35.495
P <sub>2</sub>	55.505	69.488

Point	X	Y
P <sub>3</sub>	58.995	30.025
P <sub>4</sub>	19.732	21.191

---

---

---

---

---

---

---


---

---

---

Solution:

## Contour cycles SL II, Roughing out kidney



### MAIN PROGRAM

```

%62190 G71 *
N5  G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15  T7 G17 S2500 * ..... R4
N20  G00 G40 G90 Z+100 M03 *
N25  G37P011 * ..... CONTOUR
N30  G120 ..... CONTOURDATA
      Q1=-18 ..... MILLING DEPTH
      Q2=1 ..... TOOL PATH OVERLAP
      Q3=+0,5 ..... ALLOWANCE FOR SIDE
      Q4=+0,5 ..... ALLOWANCE FOR DEPTH
      Q5=+0 ..... SURFACE COORDINATE
      Q6=+2 ..... SETUP CLEARANCE
      Q7=+10 ..... CLEARANCE HEIGHT
      Q8=+0 ..... ROUNDING RADIUS
      Q9=-1 * ..... DIRECTION OF ROTATION
N35  G122 ..... ROUGH OUT
      Q10=+10 ..... PLUNGING DEPTH
      Q11=100 ..... FEED RATE
      Q12=200 ..... FEED RATE FOR ROUGHING OUT
      Q18=0 ..... COARSE ROUGHING TOOL
      Q19=150 * ..... RECIPROCATION FEED RATE
N40  M99 *
N45  G00 Z+100 M06 *

N50  T8 G17 S2000 * ..... R5
N55  G00 G40 G90 Z+100 M03 *
N60  G123 ..... FLOOR FINISHING
      Q11=100
      Q12=200 *
N65  M99 *
N70  G124 ..... SIDE FINISHING
      Q9=-1 ..... DIRECTION OF ROTATION
      Q10=+10 ..... PLUNGING DEPTH
      Q11=100 ..... FEED RATE
      Q12=200 ..... FEED RATE FOR ROUGHING OUT
      Q14=+0 * ..... ALLOWANCE FOR SIDE
N75  M99 *

Retract tool, end N80  G00 Z+100 M30 *

```

Solution:


## Contour cycles SL II, Roughing out kidney

**SPGM**

*N85 G98L1\**  
*N90 G01 G42 X+5 Y+30 \**  
*N95 I+15 J+30 \**  
*N100 G02 X+6,645 Y+35,495 \**  
*N105 G06 X+55,505 Y+69,488 \**  
*N110 G05 X+58,995 Y+30,025 R-20 \**  
*N115 G06 X+19,732 Y+21,191 \**  
*N120 G02 X+5 Y+30 \**  
*N125 G98 L0 \**  
*N999999 %62190 G71 \**

**Task: Contour cycles SL II,  
Kidney-shaped island**

Program(s): \_\_\_\_\_  
 \_\_\_\_\_



Point	X	Y
P <sub>1</sub>	6.645	35.495
P <sub>2</sub>	55.505	69.488

Point	X	Y
P <sub>3</sub>	58.995	30.025
P <sub>4</sub>	19.732	21.191

---

---

---

---

---

---

---


---

---

---

Solution:

## Contour cycles SL II, Kidney-shaped island



### MAIN PROGRAM

```

%62191 G71 *
N5  G30 G17 X+0 Y+0 Z-20 *
N10 G31 G90 X+100 Y+100 Z+0 *
N15  T7 G17 S2500 * ..... R3
N20  G00 G40 G90 Z+100 M03 *
N25  G37 P01 1 P02 2 * ..... CONTOURS
N30  G120 ..... CONTOURDATA
      Q1=-18 ..... MILLING DEPTH
      Q2=1 ..... TOOL PATH OVERLAP
      Q3=+0,5 ..... ALLOWANCE FOR SIDE
      Q4=+0,5 ..... ALLOWANCE FOR DEPTH
      Q5=+0 ..... SURFACE COORDINATE
      Q6=+2 ..... CLEARANCE HEIGHT
      Q7=+10 ..... SETUP CLEARANCE
      Q8=+0 ..... ROUNDING RADIUS
      Q9=-1 * ..... DIRECTION OF ROTATION
N35  G122 ..... ROUGH OUT
      Q10=+10 ..... PLUNGING DEPTH
      Q11=100 ..... FEED RATE
      Q12=200 ..... FEED RATE FOR ROUGHING OUT
      Q18=0 ..... COARSE ROUGHING TOOL
      Q19=150 * ..... RECIPROICATION FEED RATE
N40  M99 *
N45  G00 Z+100 M06 *

N50  T8 G17 S2000 * ..... R4
N55  G00 G40 G90 Z+100 M03 *
N60  G123 ..... FLOOR FINISHING
      Q11=100 ..... FEEDRATE
      Q12=200 * ..... FEED RATE FOR ROUGHING OUT
N65  M99 *
N70  G124 ..... SIDE FINISHING
      Q9=-1 ..... DIRECTION OF ROTATION
      Q10=+10 ..... PLUNGING DEPTH
      Q11=100 ..... FEED RATE
      Q12=200 ..... FEED RATE FOR ROUGHING OUT
      Q14=+0 * ..... ALLOWANCE FOR SIDE
N75  M99 *

Retract tool, end N80  G00 Z+100 M30 *

```



Solution:

## Contour cycles SL II, Kidney-shaped island

**SPGM**


*N85 G98 L1 \**  
*N90 G01 G41 X+5 Y+30 \**  
*N95 I+15 J+30 \**  
*N100 G02 X+6,645 Y+35,495 \**  
*N105 G06 X+55,505 Y+69,488 \**  
*N110 G05 X+58,995 Y+30,025 R-20 \**  
*N115 G06 X+19,732 Y+21,191 \**  
*N120 G02 X+5 Y+30 \**  
*N125 G98 L0 \**

*N130 G98 L2 \**  
*N135 G01 G42 X-10 Y+10 \**  
*N140 Y+110 \**  
*N145 X+110 \**  
*N150 Y-10 \**  
*N155 X-10 \**  
*N160 G98 L0 \**  
*N999999 %62191 G71 \**



Solution:

## Datum shift and mirror images



### MAIN PROGRAM

```

%62192 G71 *
N10 G30 G17 X+0 Y+0 Z-20 *
N20 G31 G90 X+100 Y+100 Z+0 *
N30 T7 G17 S4000 *
N40 G00 G40 G90 Z+100 M03 *
N50 G54 X+50 Y+50 * ..... DATUM
N60 L1,0 *

N70 G28 X * ..... MIRROR IMAGE
N80 L1,0 *

N90 G28 X Y * ..... MIRROR IMAGE
N100 L1,0 *

N110 G28 Y * ..... MIRROR IMAGE
N120 L1,0 *

N130 G28 * ..... RESET MIRROR IMAGE
N140 G54 X+0 Y+0 * ..... RESET DATUM SHIFT

Retract tool, end      N150 G00 Z+100 M30 *
  
```

### SPGM, contour

```

N160 G98 L1 *
N170 G00 X+0 Y+0 * ..... AUXILIARY POINT R0
N180 Z+2 *
N190 G01 Z-20 F200 * ..... PLUNGING DEPTH
N200 G01 G41 X+10 Y+10 * ..... CONTOUR STARTING POINT
N200 G26 R3 * ..... APPROACH TANGENTIALLY
N210 G01 Y+45 *
N220 X+30 Y+10 *
N230 X+10 *
N240 G27 R3 * ..... DEPART TANGENTIALLY
N250 G01 G40 X+0 Y+0 *
N260 G98 L0 *
N999999 %62192 G71 *
  
```